

Deschutes County Sheriff's Office
TeNSr Channel Bank Configurations



Chn Bnk		Awbrey Butte - Prime Site				Chassis Model/Serial/Rev:															
1						891830 / 32732 / B2															
F R O N T	Card Slot	Card Slot Module				Plug-In															
	Card Slot	Part No.	Serial No.	Description	Fimware/Board Ver	1				2											
		Part No.	Serial	Item	Version	Part No.	Serial	Item	Version												
	C1	880360	017870	CPU-5 XCON	V 5.3.1 Ker 5.0.1 / B0-0																
	C2	880360	017879	BACKUP CPU-5 XCON	V 5.3.1 Ker 5.0.1 / B0-0																
	P1																				
	P2																				
	P3																				
	W1	801060	058996	WAN DUAL	E4-0	81130	059547	DSX	A1	81130	059604	DSX	A1								
	W2	801060	058995	WAN DUAL	E4-0	81130	059607	DSX	A1	81130	059453	DSX	A1								
W3	801060	036432	WAN DUAL	E4-0			DSX				DSX										
W4	801460	002197	WAN-R DUAL	E3-0	81130	031675	DSX	A1	81130	031715	DSX	A1									
F1	8901		POWER SUPPLY, AC		Lat 44-04-38.8 N Elev: 1269 M																
F2	8901		POWER SUPPLY, AC		Lon 121-19-55.1 W 4163 Ft																
B A C K	Card Slot	Card Slot Module				Plug-In															
	Card Slot	Part No.	Serial No.	Description	Firmware/Board Ver	Part No.				Serial				Item				Version			
	IF	892360	009213	INF+M T1E1*8	Rev A1-0																
	U1	816460	009303	DSM4*4	F3-0 / V2.9																
	U2	816460	009289	DSM4*4	F3-0 / V2.9																
	U3	816460	004077	DSM4*4	C9-0 / v2.9									Fred							
	U4	816460	003775	DSM4*4	F3-0 / V2.9																
	U5	816460	003884	DSM4*4	F3-0 / V2.9																
	U6	811960	024015	E&M 4W*8ER	F2-0																
	U7	8139	007987	FXO 2W*8-6	H2-0																
	U8	822560	003250	SRU-LD 232*10	A0-0 / V 1.2																
	R1					01 - 225CXD0128				06 - 225CCT0131				Prime (Mn) MTC3600 377CGT0165							
	R2					02 - 225CXD0018				07 - 225CCT0128				Prime (Bu) MTC3600 377CGT0069							
	R3					03 - 225CXD0019				08 - 225CCT0127				Prime (Re) MTC3600 377CGT0006							
	R4					04 - 225CXD0020				09 - 225CCT0129				CmbLine Fltr - Mod / 89-86A-01349							
R5					05 - 225CXP0177				10 - 225CCT0130				S/N / 58724-A3								
Harris - Mod CNSTL6-MHS		CM - Mod. CM6 - A07HYD2676A		Stratex - Mod - DXR700		DBS (02)-T5365A/680CZF0002-854.9625		Cmbnr-WIJD862-10S S/N 14661-001													
S/N - A04590A1-A1		S/N - CM101CWM0026		S/N - GPC1035596		Ferrups S/N FE18K04923		TRAK 9100-8 S/N 765													
S/N - A04590A1-A2																					

Deschutes County Sheriff's Office
TeNSr Channel Bank Configurations



Chn Bnk		Awbrey Butte - Prime Site				Chassis Model/Serial/Rev:							
2						891830 / 32947 / B2							
F R O N T		Card Slot Module				Plug-In							
	Card Slot	Part No.	Serial No.	Description	Fimware/Board Ver	1				2			
		Part No.	Serial	Item	Version	Part No.	Serial	Item	Version				
	C1	880360	017908	CPU-5 XCON	V 5.3.1 Ker 5.0.1 / B0-0								
	C2	880360	017878	BACKUP CPU-5 XCON	V 5.3.1 Ker 5.0.1 / B0-0								
	P1												
	P2												
	P3												
	W1	801060	059532	DSX+DSX WAN DUAL	E4-0	81130	061039	DSX	A1	81130	061053	DSX	A1
	W2												
W3	801060	005128	DSX+DSX WAN DUAL	E3-0	81130	061050	DSX	A1	81130	061058	DSX	A1	
W4													
F1	8901	037168	POWER SUPPLY, AC										
F2	8901	036883	POWER SUPPLY, AC										
B A C K		Card Slot Module				Plug-In							
	Card Slot	Part No.	Serial No.	Description	Firmware/Board Ver	Part No.	Serial	Item	Version				
	IF	892360	009479	INF+M T1E1*8	B1-0 / 2.9								
	U1	8164	002424	DSM-II 4W*4	F3-0 / V2.9								
	U2	8164	001110	DSM-II 4W*4	F3-0 / V2.9								
	U3	8164	009285	DSM-II 4W*4	F3-0 / V2.9	864		002745		FRED		A3	
	U4	8164	002379	DSM-II 4W*4	F3-0 / V2.9								
	U5	8164	000676	DSM-II 4W*4	F3-0 / V2.9								
	U6	811960	036329	E&M 4W *8ER	F2-0								
	U7	8125	000232	FXO 2W*4-6	D1-0								
	U8	822560	003602	SRU-LD 232*10	A0-0 / V 1.2								
	R1					Digitac Comparator							
	R2					01 - 424CWW0124 06 - 424CAR0015							
	R3					02 - 424CXP0088 07 - 424CWW0127							
	R4					03 - 424CWW0126 08 - 424CAR0016							
R5					04 - 424CAR0014 09 - 424CAR0018								
					05 - 424CWW0125 10 - 424CAR0017								

Deschutes County Sheriff's Office
TeNSr Channel Bank Configurations



Chn Bnk		Awbrey Butte - Prime Site				Chassis Model/Serial/Rev:							
3						891830 / 32949 / B2							
F R O N T	Card Slot	Card Slot Module				Plug-In							
	Card Slot	Part No.	Serial No.	Description	Firmware/Board Ver	1				2			
		Part No.	Serial	Item	Version	Part No.	Serial	Item	Version				
	C1	880360	017907	CPU-5 XCON Redundant	V 5.3.1 / B0-0								
	C2	880360	017915	CPU-5 XCON	V 5.3.1 / B0-0								
	P1												
	P2												
	P3												
	W1	801060	059529	DSX+DSX WAN DUAL	E4-0	81130	061047	DSX	A1	81130	061041	DSX	A1
	W2	801060	059150	DSX+DSX WAN DUAL	E4-0	81130	059616	DSX	A1	81130	059541	DSX	A1
W3	801060	005148	DSX+DSX WAN DUAL	E3-0	81130	061046	DSX	A1	81130	061031	DSX	A1	
W4	801460	005030	WAN-R DUAL	E3-0	81130	059454	DSX	A1	81130	059545	DSX	A1	
F1	8901	037095	POWER SUPPLY, AC										
F2	8901	037000	POWER SUPPLY, AC										
B A C K	Card Slot	Card Slot Module				Plug-In							
	Card Slot	Part No.	Serial No.	Description	Firmware/Board Ver	Part No.		Serial		Item		Version	
	IF	892360	009484	INF+M T1E1*8	B1-0								
	U1	816460	009290	DSM-II 4W*4	Rev F3-0 / V 2.9								
	U2	816460	003861	DSM-II 4W*4	Rev F3-0 / V 2.9								
	U3	816460	009298	DSM-II 4W*4 FRED	Rev F3-0 / V 2.9	864		002713		Fred		A3	
	U4	816460	009274	DSM-II 4W*4	Rev F3-0 / V 2.9								
	U5	816460	003839	DSM-II 4W*4	Rev F3-0 / V 2.9								
	U6	816460	009296	DSM-II 4W*4	Rev F3-0 / V 2.9								
	U7	811960	036342	E&M 4-W*8	Rev F2-0								
	U8	822560	003351	SRU-LD 232*10	Rev A0-0 / V 1.2								
	R1												
	R2												
	R3												
	R4												
R5													

Deschutes County Sheriff's Office
TeNSr Channel Bank Configurations



Chn Bnk		Awbrey Butte - Prime Site				Chassis Model/Serial/Rev: 891830 / 32592 / B2							
4													
F R O N T	Card Slot	Card Slot Module				Plug-In							
	Card Slot	Part No.	Serial No.	Description	Firmware/Board Ver	1				2			
						Part No.	Serial	Item	Version	Part No.	Serial	Item	Version
	C1	880360	017867	CPU-5 XCON RDNT	5.3.1 / B0-0								
	C2	880360	017876	CPU-5 XCON SSSS	5.3.1 Ker 5.0.1 / B0-0								
	P1												
	P2												
	P3												
	W1	801060	058998	WAN DUAL	Rev E4-0	81130	059614	DSX	A1	81130	059551	DSX	A1
	W2	801060	059153	WAN DUAL	Rev E4-0	81130	059609	DSX	A1	81130	059611	DSX	A1
	W3	801060	058804	WAN DUAL	Rev E4-0	81130	059542	DSX	A1	81130	059608	DSX	A1
	W4	801460	005023	WAN-R DUAL	Rev E3-0	81130	059580	DSX	A1	81130	059462	DSX	A1
	F1	8901	036526	POWER SUPPLY, AC	H9								
	F2	8901	036709	POWER SUPPLY, AC	H9								
B A C K	Card Slot	Card Slot Module				Plug-In							
	Card Slot	Part No.	Serial No.	Description	Firmware/Board Ver	Part No.				Serial			
	IF	892360	001805	INF+M T1E1*8	Rev A1-0								
	U1	816460	009507	DSM-II 4W*4	Rev F3-0 / V 2.9								
	U2	816460	009294	DSM-II 4W*4	Rev F3-0 / V 2.9								
	U3	816460	009271	DSM-II 4W*4 FRED	Rev F3-0 / V 2.9	864		002691		FRED		A3	
	U4	816460	009269	DSM-II 4W*4	Rev F3-0 / V 2.9								
	U5	816460	009280	DSM-II 4W*4	Rev F3-0 / V 2.9								
	U6	811960	011606	E&M 4W*8ER	Rev F2-0								
	U7												
	U8	822560	003330	SRU-LD 232*10	A0-0 / V 1.2								
	R1												
	R2												
	R3												
	R4												
	R5												

Deschutes County Sheriff's Office
TeNSr Channel Bank Configurations



Chn Bnk 5					Gray Butte								Chassis Model/Serial/Rev: 891823 / 003512 / A1			
F R O N T	Card Slot	Card Slot Module				Plug-In										
	Card Slot	Part No.	Serial No.	Description	Firmware/Board Ver	1				2						
	Part No.	Serial	Item	Version	Part No.	Serial	Item	Version	Part No.	Serial	Item	Version				
	C1	8800	018933	CPU-3 BCON	Rev D2-0 / F 3.9.3											
	C2															
	P1															
	P2															
	P3															
	W1	801060	036410	WAN DUAL	Rev E4-0			DSX				DSX				
	W2															
W3																
W4																
F1	8901		POWER SUPPLY, AC		Lat: N 44 25 06.6				Elev. 1536 m							
F2	8901		POWER SUPPLY, AC		Lon: W 121 06 04.0				5039 ft							
B A C K	Card Slot	Card Slot Module				Plug-In										
	Card Slot	Part No.	Serial No.	Description	Firmware/Board Ver	Part No.	Serial	Item	Version	Part No.	Serial	Item	Version			
	IF	892360	009217	INF+M T1E1*8	Rev B1-0											
	U1	816460	010199	DSM-II 4W*4 FRED	Rev F3-0 / V 2.9	864				FRED						
	U2	816460	010060	DSM-II 4W*4	Rev F3-0 / V 2.9											
	U3	816460	004472	DSM-II 4W*4	Rev C9-0 / V 2.9											
	U4															
	U5															
	U6	8125	000761	FXS 2W *4-6	Rev A3-0											
	U7	811960	011589	E&M 4W*8ER	Rev F2-0											
	U8	822560	003345	SRU-LD 232*10	A0-0 V 1.2											
	R1	8906		RING GENERATOR		01 - 225CXD0021	06 - 225CDT0050	RESC - MTC 3600 - S/N 377CDT0065								
	R2					02 - 225CXD0022	07 - 225CDT0051	TX-RX Filter Mod 89-86A-01349								
	R3					03 - 225CXD0024	08 - 225CDT0052	S/N 58724-A1								
	R4					04 - 225CXD0025	09 - 225CDT0053	Cmbnr-WJD860-S S/N 382434-001								
R5	8903		48VDC CONVERTER		05 - 225CXP0178	10 - 225CDT0054	TRAK 9100-9 S/N 2331									
California Microwave - Mod / CM6, S/N - CM101CWM0027					DBS (03) - 680CZF0003 - 860.9875								S/N 382449-001			

Deschutes County Sheriff's Office
TeNSr Channel Bank Configurations



Chn Bnk		Fivemile Butte				Chassis Model/Serial/Rev:			
6						891830 / 015008 / B1			
F R O N T		Card Slot Module				Plug-In			
	Card Slot	Part No.	Serial No.	Description	Fimware/Board Ver	1		2	
	Part No.	Serial	Item	Version	Part No.	Serial	Item	Version	
	C1	8800	013267	CPU-3 BCON	Rev E0-0 / Ver 3.9.0				
	C2								
	P1								
	P2								
	P3								
	W1	801060	037335	WAN DUAL	Rev E0-0			DSX	
	W2								
W3									
W4									
F1	8901		POWER SUPPLY, AC		Lat: N 44 21 04.3 Elev. 1203 m				
F2	8901		POWER SUPPLY, AC		Lon: W 121 41 28.9 3947 ft				
B A C K		Card Slot Module				Plug-In			
	Card Slot	Part No.	Serial No.	Description	Firmware/Board Ver	Part No.	Serial	Item	Version
	IF	892360	008693	INF+M T1E1*8	Rev B0-0				
	U1	816460	003365	DSM-II 4W*4 FRED	F3-0 / Ver 2.9	864		FRED	
	U2	816460	003363	DSM-II 4W*4	F3-0 / Ver 2.9				
	U3	816460	009425	DSM-II 4W*4	F3-0 / Ver 2.9				
	U4								
	U5								
	U6	812960	046449	FXS 2W*8	Rev C1-0				
	U7	811960	024020	E&M 4W*8ER	Rev F2-0				
	U8	822560	003604	SRU-LD 232*10	Rev A0-0 / Ver 1.2				
	R1					01 - 225CAP0317	06 - 225CDT0055	RESC - MTC 3600 - 377CGT0001	
	R2					02 - 225CAP0318	07 - 225CDT0056	TX-RX Filter Mod 89-86A-01349	
	R3					03 - 225CAP0319	08 - 225CDT0057	S/N 58724-A2	
	R4					04 - 225CAP0320	09 - 225CDT0058	Cmbnr - WIJD862-10S - S/N / 14660-001	
R5					05 - 225CAP0321	10 - 225CDT0059	TRAK 9100-9 - S/N 2328		
Harris - Mod CNSTL6-MHS		NewMar - Mod / 48-15		MTR2000(T5544) S/N 512CHM0134		M-coupler TDF6491A1-1 S/N 0034139864			
S/N - A04590B1-3		S/N / 0165995		Duplexer (Q2330E) S/N CC36333-1-2		Ferrups (FE7KVA) - FE7K03265			

Deschutes County Sheriff's Office
TeNSr Channel Bank Configurations



Chn Bnk		Spring River Butte				Chassis Model/Serial/Rev:			
7						891830 / 015367 / B1			
F R O N T		Card Slot Module				Plug-In			
	Card Slot	Part No.	Serial No.	Description	Fimware/Board Ver	1		2	
	Part No.	Serial	Item	Version	Part No.	Serial	Item	Version	
	C1	8800	013278	CPU-3 BCON	F 3.9.0 / Rev D2-0				
	C2								
	P1								
	P2								
	P3								
	W1	801060	037334	WAN DUAL	Rev E4-0			DSX	
	W2								
W3									
W4									
F1	8901		POWER SUPPLY, AC		Lat: N 43 52 25.8		Elev. 1487 m		
F2	8901		POWER SUPPLY, AC		Lon: W 121 30 17.0		4879 ft		
B A C K		Card Slot Module				Plug-In			
	Card Slot	Part No.	Serial No.	Description	Firmware/Board Ver	Part No.	Serial	Item	Version
	IF	892360	008558	INF+M T1E1*8	B0-0				
	U1	816460	003784	DSM-II 4W*4 FRED	Rev F3-0 / V 2.9	864		FRED	
	U2	816460	003415	DSM-II 4W*4	Rev F3-0 / V 2.9				
	U3	816460	009288	DSM-II 4W*4	Rev F3-0 / V 2.9				
	U4								
	U5								
	U6	812960	046439	FXS 2W*8	Rev C1-0				
	U7	811960	024009	E&M 4W*8ER	Rev F2-0				
	U8	822560	003300	SRU-LD 232*10	Rev A0-0 / V 1.2				
	R1					01 - 225CAP0322	06 - 225CDT0061	RESC - MTC 3600 - KV285	
	R2					02 - 225CAP0323	07 - 225CDT0062	TX-RX Filter Mod 89-86A-01349	
	R3					03 - 225CAP0324	08 - 225CDT0063	S/N 58724-A2	
	R4					04 - 225CAP0325	09 - 225CDT0064	Cmbnr - WIJD862-10S - S/N / 14660-001	
R5					05 - 225CAP0326	10 - 225CDT0065	TRAK 9100-9 - S/N 2332		
						M-coupler TDF6491A1-1 S/N 0034139864			
						Ferrups (FE7KVA) - FE7K03265			

Deschutes County Sheriff's Office
TeNSr Channel Bank Configurations



Chn Bnk		Wampus Butte				Chassis Model/Serial/Rev:							
8						891823 / 003414 / A1							
F R O N T	Card Slot	Card Slot Module				Plug-In							
	Card Slot	Part No.	Serial No.	Description	Firmware/Board Ver	1				2			
	Part No.	Serial	Item	Version	Part No.	Serial	Item	Version	Part No.	Serial	Item	Version	
	C1	8802	014998	CPU-3 BCON	F3.9.0 / Rev D2-0								
	C2												
	P1												
	P2												
	P3												
	W1	801060	010430	WAN DUAL	Rev E3-0			DSX				DSX	
	W2												
W3													
W4													
F1	8901		POWER SUPPLY, AC		Lat: N 43 41 58.9				Elev. 1519 m				
F2	8901		POWER SUPPLY, AC		Lon: W 121 37 19.0				4984 ft				
B A C K	Card Slot	Card Slot Module				Plug-In							
	Card Slot	Part No.	Serial No.	Description	Firmware/Board Ver	Part No.	Serial	Item	Version	Part No.	Serial	Item	Version
	IF	892360	000637	INF+M T1E1*8	Rev A1-0								
	U1	816460	004465	DSM-II 4W*4 FRED	Rev C9-0 / V 2.9	864		FRED					
	U2	816460	005094	DSM-II 4W*4	Rev C9-0 / V 2.9								
	U3	816460	009281	DSM-II 4W*4	Rev F3-0 / V 2.9								
	U4												
	U5												
	U6	812960	046436	FXS 2W*8-6	Rev C1-0								
	U7	811960	011656	E&M 4W*8ER	Rev F2-0								
	U8	822560	003297	SRU-LD 232*10	Rev A0-0 / V 1.2								
	R1					01 - 225CDT0040	06 - 225CDT0045	RESC - MTC 3600 - ?????					
	R2					02 - 225CDT0041	07 - 225CDT0046	TX-RX Filter Mod 89-86A-01349					
	R3					03 - 225CDT0042	08 - 225CDT0047	S/N 58724-A2					
	R4					04 - 225CDT0043	09 - 225CDT0048	Cmbnr - WIJD862-10S S/N - 14657-001					
R5					05 - 225CDT0044	10 - 225CDT0049	TRAK 9100-9 - S/N 2329						
							Multicoupler - S/N - 3-16833-F						

Deschutes County Sheriff's Office
TeNSr Channel Bank Configurations



Chn Bnk 9Mount Bachelor - Pine Marten 9-18-08					Chassis Model/Serial/Rev: 891830 / 046927 /B2								
F R O N T	Card Slot	Card Slot Module				Plug-In							
	Card Slot	Part No.	Serial No.	Description	Fimware/Board Ver	1				2			
	Part No.	Serial	Item	Version	Part No.	Serial	Item	Version					
	C1	880460	08942	CPU-RCON	V 3.9.3 / Rev D1-0								
	C2												
	P1												
	P2												
	P3												
	W1	801060	012473	WAN DUAL SS	Rev F0-0			DSX				DSX	
	W2												
W3													
W4													
F1	8901		POWER SUPPLY, AC		Lat: N 43 59 26.4				Elev. 2360 m				
F2	8901		POWER SUPPLY, AC		Lon: W 121 41 11.5				7743 Ft				
B A C K	Card Slot	Card Slot Module				Plug-In							
	Card Slot	Part No.	Serial No.	Description	Firmware/Board Ver	Part No.	Serial	Item	Version				
	IF	892360	020108	INF+M T1E1*8	Rev C0-0								
	U1	816460	014987	DSM-II 4W*4	Rev F3-0 Ver 2.9								
	U2	816460	011550	DSM-II 4W*4	Rev F3-0 Ver 2.9	864							
	U3	816460	014984	DSM-II 4W*4	Rev F3-0 Ver 2.9								
	U4												
	U5												
	U6	812960	045356	FXS 2W*8-6	Rev C1-0								
	U7	811960	036221	E&M 4W*8ER	Rev F2-0								
	U8	822560	009391	SRU-LD 232*10	Rev A1-0 / Ver 1.2								
	R1	8906		RING GENERATOR		01 - 225CJK0081	06 - 225CJK0075	RESC - MTC 3600 - KV434					
	R2					02 - 225CJK0082	07 - 225CJK0077	TX-RX Filter Mod 89-86A-01349					
	R3					03 - 225CJK0083	08 - 225CJK0078	S/N 58724-A2					
	R4					04 - 225CJK0076	09 - 225CJK0079	Cmbnr - WIJD862-10S - S/N / 14660-001					
R5	8903		48VDC CONVERTER		05 - 225CJK0074	10 - 225CJK0080	TRAK 9100-9 - S/N ????						
					M-coupler TDF6491A1-1 S/N 0034139864								
					Eaton (9170+) - EB203T0005								

Deschutes County Sheriff's Office
TeNSr Channel Bank Configurations



Chn Bnk		Antelope Butte				Chassis Model/Serial/Rev:							
10						891830 / 21353 /							
F R O N T		Card Slot Module				Plug-In							
	Card Slot	Part No.	Serial No.	Description	Fimware/Board Ver	1				2			
						Part No.	Serial	Item	Version	Part No.	Serial	Item	Version
	C1	880460	005593	CPU-RCON	Rev C1-0, Ver 3.9.3								
	C2												
	P1												
	P2												
	P3												
	W1	801060	058997	WAN DUAL SS	Rev E4	811	059546	DSX		811	059620	DSX	
	W2												
W3													
W4													
F1	8901	036764	POWER SUPPLY, AC		Lat = N 43 48 41.8				Elev 1858m				
F2	8901	036735	POWER SUPPLY, AC		Lon: W 120 52 27.9				6096 ft				
B A C K		Card Slot Module				Plug-In							
	Card Slot	Part No.	Serial No.	Description	Firmware/Board Ver	Part No.		Serial		Item		Version	
	IF	892360	015024	INTF+Modem T1E1*8	Rev B0-0								
	U1	816460	009297	DSM-II 4W*4 FRED	Rev F3-0 / V 2.9	864		002691		FRED			
	U2	816460	001458	DSM-II 4W*4	Rev F3-0 / V 2.9								
	U3	816460	003831	DSM-II 4W*4	Rev F3-0 / V 2.9								
	U4												
	U5												
	U6	812960	040543	FXS 2W*8-6	Rev C1-0								
	U7	811960	023683	E&M 4W*8ER	Rev F2-0								
	U8	822560	003248	SRU-LD 232*10	Rev A0-0 / V 1.2								
	R1	8906		RING GENERATOR		01 - 225CDT0040	06 - 225CDT0045	RESC - MTC 3600 - 377CGT0009					
	R2					02 - 225CDT0041	07 - 225CDT0046	TX-RX Filter Mod 89-86A-01349					
	R3					03 - 225CDT0042	08 - 225CDT0047	S/N 58724-A2					
	R4					04 - 225CDT0043	09 - 225CDT0048	Cmbnr-WIJD862-10S - S/N - 14657-001					
R5	8903		48VDC CONVERTER		05 - 225CDT0044	10 - 225CDT0049	TRAK 9100-9 - S/N 2330						
Stratex - Mod. - RMA-04DS1-2-48					ONAN - Mod. LTB-5618532					Multicoupler - S/N - 3-16833-F			
S/N - GPC1035596					S/N - D030488702								
					Ferrups S/N FE12.5K02917								

Deschutes County Sheriff's Office
TeNSr Channel Bank Configurations



Chn Bnk 11 Hampton Butte - Future Chassis Model/Serial/Rev: 891830 / XXXXXX / XX													
F R O N T	Card Slot	Card Slot Module				Plug-In							
		Part No.	Serial No.	Description	Firmware/Board Ver	1				2			
	C1					Part No.	Serial	Item	Version	Part No.	Serial	Item	Version
	C2												
	P1												
	P2												
	P3												
	W1												
	W2												
	W3												
B A C K	W4												
	F1												
	F2												
	Card Slot	Card Slot Module				Plug-In							
		Part No.	Serial No.	Description	Firmware/Board Ver	Part No.				Serial			
	IF			INF+M T1E1*8									
	U1												
	U2												
	U3												
	U4												
	U5												
	U6												
	U7												
	U8			SRU-LD 232*10									
	R1												
	R2												
	R3												
	R4												
	R5												

Deschutes County Sheriff's Office
TeNSr Channel Bank Configurations



Chn Bnk		Awbrey Butte - Microwave to DCSO				Chassis Model/Serial/Rev:							
12						891823 / 003417 / A1							
F R O N T	Card Slot	Card Slot Module				Plug-In							
	Card Slot	Part No.	Serial No.	Description	Firmware/Board Ver	1				2			
						Part No.	Serial	Item	Version	Part No.	Serial	Item	Version
	C1	880360	009625	CPU-5 XCON	FW5.3.0,KER5.0.1,REVB0								
	C2	880360	009672	CPU-5 XCON	FW5.3.0,KER5.0.1,REVB0								
	P1												
	P2												
	P3												
	W1	801060	0096202	WAN DUAL	Rev E2	811	007487	DSX	Rev F0	811	036771	DSX	Rev F0
	W2												
	W3												
	W4	8014	001432	WAN-R DUAL	Rev D4	811	008112	DSX	Rev F0	811	008125	DSX	Rev F0
B A C K	F1	8901	031529	POWER SUPPLY, AC	Rev H9								
	F2	8901	028631	POWER SUPPLY, AC	Rev H9								
	Card Slot	Card Slot Module				Plug-In							
	Card Slot	Part No.	Serial No.	Description	Firmware/Board Ver	Part No.	Serial	Item	Version				
	IF	892360	014580	INF+M T1E1*8	Rev C0-0								
	U1												
	U2	811960	023733	E&M 4W*8	Rev F2								
	U3	811960	036359	E&M 4W*8	Rev F2								
	U4	811960		E&M 4W*8									
	U5												
	U6	810860	002116	E&M 2W*8	Rev A5								
	U7												
	U8	822560	002363	SRU-LD 232*10	Fw1.2,Ker1.0,RevA1								
	R1												
	R2												
	R3												
	R4												
	R5												

Deschutes County Sheriff's Office
TeNSr Channel Bank Configurations



Chn Bnk		DCSO 911 Equipment Room - Microwave to Awbrey				Chassis Model/Serial/Rev:							
13						891823 / 003509 / A1							
F R O N T	Card Slot	Card Slot Module				Plug-In							
	Card Slot	Part No.	Serial No.	Description	Firmware/Board Ver	1				2			
	Part No.	Serial	Item	Version	Part No.	Serial	Item	Version	Part No.	Serial	Item	Version	
	C1	880360	002064	CPU-5 XCON	CPU 5.0.0,Ker 5.0.0, Rev A0								
	C2	880360	002022	CPU-5 XCON	CPU 5.0.0,Ker 5.0.0, Rev A0								
	P1												
	P2												
	P3												
	W1	801060	036245	WAN DUAL	Rev E4	81130	031328	DSX	A1	81130	031545	DSX	A1
	W2												
W3													
W4	801460	000245	WAN-R DUAL	Rev E1	811	036777	DSX	F0	811	036747	DSX	F0	
F1	8901	031547	POWER SUPPLY, AC	Rev H9									
F2	8901	043626	POWER SUPPLY, AC	Rev H9									
B A C K	Card Slot	Card Slot Module				Plug-In							
	Card Slot	Part No.	Serial No.	Description	Firmware/Board Ver	Part No.	Serial	Item	Version	Part No.	Serial	Item	Version
	IF	892360	001794	INF+M T1E1*8	Rev A1								
	U1												
	U2	811960	024021	E&M 4W*8	Rev F2								
	U3	811960	024006	E&M 4W*8	Rev F2								
	U4	811960	024013	E&M 4W*8	Rev F2								
	U5												
	U6	810860	001740	E&M 2W*8	A5								
	U7												
	U8	822560	003342	SRU-LD 232*10	Fw 1.2, KER 1.0, Rev B2								
	R1												
	R2												
	R3												
	R4												
R5													

Deschutes County Sheriff's Office
TeNSr Channel Bank Configurations



Chn Bnk		Awbrey Butte - Prime Site				Chassis Model/Serial/Rev:											
1						891830 / 32732 / B2											
F R O N T		Card Slot Module				Plug-In											
	Card Slot	Part No.	Serial No.	Description	Fimware/Board Ver	1				2							
						Part No.	Serial	Item	Version	Part No.	Serial	Item	Version				
	C1	880360	017870	CPU-5 XCON	V 5.3.1 Ker 5.0.1 / B0-0												
	C2	880360	017879	BACKUP CPU-5 XCON	V 5.3.1 Ker 5.0.1 / B0-0												
	P1																
	P2																
	P3																
	W1	801060	058996	WAN DUAL	E4-0	81130	059547	DSX	A1	81130	059604	DSX	A1				
	W2	801060	058995	WAN DUAL	E4-0	81130	059607	DSX	A1	81130	059453	DSX	A1				
W3	801060	036432	WAN DUAL	E4-0			DSX				DSX						
W4	801460	002197	WAN-R DUAL	E3-0	81130	031675	DSX	A1	81130	031715	DSX	A1					
F1	8901		POWER SUPPLY, AC		Lat 44-04-38.8 N Elev: 1269 M												
F2	8901		POWER SUPPLY, AC		Lon 121-19-55.1 W 4163 Ft												
B A C K		Card Slot Module				Plug-In											
	Card Slot	Part No.	Serial No.	Description	Firmware/Board Ver	Part No.				Serial				Item		Version	
	IF	892360	009213	INF+M T1E1*8	Rev A1-0												
	U1	816460	009303	DSM4*4	F3-0 / V2.9												
	U2	816460	009289	DSM4*4	F3-0 / V2.9												
	U3	816460	004077	DSM4*4	C9-0 / v2.9												
	U4	816460	003775	DSM4*4	F3-0 / V2.9												
	U5	816460	003884	DSM4*4	F3-0 / V2.9												
	U6	811960	024015	E&M 4W*8ER	F2-0												
	U7	8139	007987	FXO 2W*8-6	H2-0												
	U8	822560	003250	SRU-LD 232*10	A0-0 / V 1.2												
	R1					01 - 225CXD0128	06 - 225CCT0131	Prime (Mn) MTC3600 377CGT0165									
	R2					02 - 225CXD0018	07 - 225CCT0128	Prime (Bu) MTC3600 377CGT0069									
	R3					03 - 225CXD0019	08 - 225CCT0127	Prime (Re) MTC3600 377CGT0006									
	R4					04 - 225CXD0020	09 - 225CCT0129	CmbLine Fltr - Mod / 89-86A-01349									
R5					05 - 225CXP0177	10 - 225CCT0130	S/N / 58724-A3										
Harris - Mod CNSTL6-MHS		CM - Mod. CM6 - A07HYD2676A		Stratex - Mod - DXR700		DBS (02)-T5365A/680CZF0002-854.9625		Cmbnr-WIJD862-10S S/N 14661-001									
S/N - A04590A1-A1		S/N - CM101CWM0026		S/N - GPC1035596		Ferrups S/N FE18K04923		TRAK 9100-8 S/N 765									
S/N - A04590A1-A2																	

Deschutes County Sheriff's Office
TeNSr Channel Bank Configurations



Chn Bnk		Awbrey Butte - Prime Site				Chassis Model/Serial/Rev:							
2						891830 / 32947 / B2							
F R O N T		Card Slot Module				Plug-In							
	Card Slot	Part No.	Serial No.	Description	Fimware/Board Ver	1				2			
						Part No.	Serial	Item	Version	Part No.	Serial	Item	Version
	C1	880360	017908	CPU-5 XCON	V 5.3.1 Ker 5.0.1 / B0-0								
	C2	880360	017878	BACKUP CPU-5 XCON	V 5.3.1 Ker 5.0.1 / B0-0								
	P1												
	P2												
	P3												
	W1	801060	059532	DSX+DSX WAN DUAL	E4-0	81130	061039	DSX	A1	81130	061053	DSX	A1
	W2												
W3	801060	005128	DSX+DSX WAN DUAL	E3-0	81130	061050	DSX	A1	81130	061058	DSX	A1	
W4													
F1	8901	037168	POWER SUPPLY, AC										
F2	8901	036883	POWER SUPPLY, AC										
B A C K		Card Slot Module				Plug-In							
	Card Slot	Part No.	Serial No.	Description	Firmware/Board Ver	Part No.		Serial		Item		Version	
	IF	892360	009479	INF+M T1E1*8	B1-0 / 2.9								
	U1	8164	002424	DSM-II 4W*4	F3-0 / V2.9								
	U2	8164	001110	DSM-II 4W*4	F3-0 / V2.9								
	U3	8164	009285	DSM-II 4W*4	F3-0 / V2.9	864		002745		FRED		A3	
	U4	8164	002379	DSM-II 4W*4	F3-0 / V2.9								
	U5	8164	000676	DSM-II 4W*4	F3-0 / V2.9								
	U6	811960	036329	E&M 4W *8ER	F2-0								
	U7	8125	000232	FXO 2W*4-6	D1-0								
	U8	822560	003602	SRU-LD 232*10	A0-0 / V 1.2								
	R1					Digitac Comparator							
	R2					01 - 424CWW0124 06 - 424CAR0015							
	R3					02 - 424CXP0088 07 - 424CWW0127							
	R4					03 - 424CWW0126 08 - 424CAR0016							
R5					04 - 424CAR0014 09 - 424CAR0018								
					05 - 424CWW0125 10 - 424CAR0017								

Digitac Comparator
01 - 424CWW0124 06 - 424CAR0015
02 - 424CXP0088 07 - 424CWW0127
03 - 424CWW0126 08 - 424CAR0016
04 - 424CAR0014 09 - 424CAR0018
05 - 424CWW0125 10 - 424CAR0017

Deschutes County Sheriff's Office
TeNSr Channel Bank Configurations



Chn Bnk		Awbrey Butte - Prime Site				Chassis Model/Serial/Rev: 891830 / 32949 / B2							
3													
F R O N T	Card Slot	Card Slot Module				Plug-In							
	Card Slot	Part No.	Serial No.	Description	Firmware/Board Ver	1				2			
						Part No.	Serial	Item	Version	Part No.	Serial	Item	Version
	C1	880360	017907	CPU-5 XCON Redundant	V 5.3.1 / B0-0								
	C2	880360	017915	CPU-5 XCON	V 5.3.1 / B0-0								
	P1												
	P2												
	P3												
	W1	801060	059529	DSX+DSX WAN DUAL	E4-0	81130	061047	DSX	A1	81130	061041	DSX	A1
	W2	801060	059150	DSX+DSX WAN DUAL	E4-0	81130	059616	DSX	A1	81130	059541	DSX	A1
	W3	801060	005148	DSX+DSX WAN DUAL	E3-0	81130	061046	DSX	A1	81130	061031	DSX	A1
	W4	801460	005030	WAN-R DUAL	E3-0	81130	059454	DSX	A1	81130	059545	DSX	A1
B A C K	F1	8901	037095	POWER SUPPLY, AC									
	F2	8901	037000	POWER SUPPLY, AC									
	Card Slot	Card Slot Module				Plug-In							
	Card Slot	Part No.	Serial No.	Description	Firmware/Board Ver	Part No.	Serial		Item	Version			
	IF	892360	009484	INF+M T1E1*8	B1-0								
	U1	816460	009290	DSM-II 4W*4	Rev F3-0 / V 2.9								
	U2	816460	003861	DSM-II 4W*4	Rev F3-0 / V 2.9								
	U3	816460	009298	DSM-II 4W*4 FRED	Rev F3-0 / V 2.9	864	002713		Fred	A3			
	U4	816460	009274	DSM-II 4W*4	Rev F3-0 / V 2.9								
	U5	816460	003839	DSM-II 4W*4	Rev F3-0 / V 2.9								
	U6	816460	009296	DSM-II 4W*4	Rev F3-0 / V 2.9								
	U7	811960	036342	E&M 4-W*8	Rev F2-0								
	U8	822560	003351	SRU-LD 232*10	Rev A0-0 / V 1.2								
	R1												
	R2												
	R3												
	R4												
	R5												

Deschutes County Sheriff's Office
TeNSr Channel Bank Configurations



Chn Bnk 4					Chassis Model/Serial/Rev: 891830 / 32592 / B2								
F R O N T	Card Slot	Card Slot Module				Plug-In							
		Part No.	Serial No.	Description	Firmware/Board Ver	1				2			
		Part No.	Serial	Item	Version	Part No.	Serial	Item	Version				
	C1	880360	017867	CPU-5 XCON RDNT	5.3.1 / B0-0								
	C2	880360	017876	CPU-5 XCON SSSS	5.3.1 Ker 5.0.1 / B0-0								
	P1												
	P2												
	P3												
	W1	801060	058998	WAN DUAL	Rev E4-0	81130	059614	DSX	A1	81130	059551	DSX	A1
	W2	801060	059153	WAN DUAL	Rev E4-0	81130	059609	DSX	A1	81130	059611	DSX	A1
W3	801060	058804	WAN DUAL	Rev E4-0	81130	059542	DSX	A1	81130	059608	DSX	A1	
W4	801460	005023	WAN-R DUAL	Rev E3-0	81130	059580	DSX	A1	81130	059462	DSX	A1	
F1	8901	036526	POWER SUPPLY, AC	H9									
F2	8901	036709	POWER SUPPLY, AC	H9									
B A C K	Card Slot	Card Slot Module				Plug-In							
		Part No.	Serial No.	Description	Firmware/Board Ver	Part No.	Serial	Item	Version				
	IF	892360	001805	INF+M T1E1*8	Rev A1-0								
	U1	816460	009507	DSM-II 4W*4	Rev F3-0 / V 2.9								
	U2	816460	009294	DSM-II 4W*4	Rev F3-0 / V 2.9								
	U3	816460	009271	DSM-II 4W*4 FRED	Rev F3-0 / V 2.9	864	002691		FRED		A3		
	U4	816460	009269	DSM-II 4W*4	Rev F3-0 / V 2.9								
	U5	816460	009280	DSM-II 4W*4	Rev F3-0 / V 2.9								
	U6	811960	011606	E&M 4W*8ER	Rev F2-0								
	U7												
	U8	822560	003330	SRU-LD 232*10	A0-0 / V 1.2								
	R1												
	R2												
	R3												
	R4												
R5													

Deschutes County Sheriff's Office
TeNSr Channel Bank Configurations



Chn Bnk 5					Gray Butte								Chassis Model/Serial/Rev: 891823 / 003512 / A1			
F R O N T		Card Slot Module				Plug-In										
	Card Slot	Part No.	Serial No.	Description	Firmware/Board Ver	1				2						
						Part No.	Serial	Item	Version	Part No.	Serial	Item	Version			
	C1	8800	018933	CPU-3 BCON	Rev D2-0 / F 3.9.3											
	C2															
	P1															
	P2															
	P3															
	W1	801060	036410	WAN DUAL	Rev E4-0			DSX				DSX				
	W2															
W3																
W4																
F1	8901		POWER SUPPLY, AC		Lat: N 44 25 06.6 Elev. 1536 m											
F2	8901		POWER SUPPLY, AC		Lon: W 121 06 04.0 5039 ft											
B A C K		Card Slot Module				Plug-In										
	Card Slot	Part No.	Serial No.	Description	Firmware/Board Ver	Part No.		Serial		Item		Version				
	IF	892360	009217	INF+M T1E1*8	Rev B1-0											
	U1	816460	010199	DSM-II 4W*4 FRED	Rev F3-0 / V 2.9	864				FRED						
	U2	816460	010060	DSM-II 4W*4	Rev F3-0 / V 2.9											
	U3	816460	004472	DSM-II 4W*4	Rev C9-0 / V 2.9											
	U4															
	U5															
	U6	8125	000761	FXS 2W *4-6	Rev A3-0											
	U7	811960	011589	E&M 4W*8ER	Rev F2-0											
	U8	822560	003345	SRU-LD 232*10	A0-0 V 1.2											
	R1	8906		RING GENERATOR		01 - 225CXD0021		06 - 225CDT0050		RESC - MTC 3600 - S/N 377CDT0065						
	R2					02 - 225CXD0022		07 - 225CDT0051		TX-RX Filter Mod 89-86A-01349						
	R3					03 - 225CXD0024		08 - 225CDT0052		S/N 58724-A1						
	R4					04 - 225CXD0025		09 - 225CDT0053		Cmbnr-WJD860-S S/N 382434-001						
R5	8903		48VDC CONVERTER		05 - 225CXP0178		10 - 225CDT0054		TRAK 9100-9 S/N 2331							
California Microwave - Mod / CM6, S/N - CM101CWM0027					DBS (03) - 680CZF0003 - 860.9875 S/N 382449-001											

Deschutes County Sheriff's Office
TeNSr Channel Bank Configurations



Chn Bnk		Fivemile Butte				Chassis Model/Serial/Rev:			
6						891830 / 015008 / B1			
F R O N T		Card Slot Module				Plug-In			
	Card Slot	Part No.	Serial No.	Description	Fimware/Board Ver	1		2	
	Part No.	Serial	Item	Version	Part No.	Serial	Item	Version	
	C1	8800	013267	CPU-3 BCON	Rev E0-0 / Ver 3.9.0				
	C2								
	P1								
	P2								
	P3								
	W1	801060	037335	WAN DUAL	Rev E0-0			DSX	
	W2								
W3									
W4									
F1	8901		POWER SUPPLY, AC		Lat: N 44 21 04.3 Elev. 1203 m				
F2	8901		POWER SUPPLY, AC		Lon: W 121 41 28.9 3947 ft				
B A C K		Card Slot Module				Plug-In			
	Card Slot	Part No.	Serial No.	Description	Firmware/Board Ver	Part No.	Serial	Item	Version
	IF	892360	008693	INF+M T1E1*8	Rev B0-0				
	U1	816460	003365	DSM-II 4W*4 FRED	F3-0 / Ver 2.9	864		FRED	
	U2	816460	003363	DSM-II 4W*4	F3-0 / Ver 2.9				
	U3	816460	009425	DSM-II 4W*4	F3-0 / Ver 2.9				
	U4								
	U5								
	U6	812960	046449	FXS 2W*8	Rev C1-0				
	U7	811960	024020	E&M 4W*8ER	Rev F2-0				
	U8	822560	003604	SRU-LD 232*10	Rev A0-0 / Ver 1.2				
	R1					01 - 225CAP0317	06 - 225CDT0055	RESC - MTC 3600 - 377CGT0001	
	R2					02 - 225CAP0318	07 - 225CDT0056	TX-RX Filter Mod 89-86A-01349	
	R3					03 - 225CAP0319	08 - 225CDT0057	S/N 58724-A2	
	R4					04 - 225CAP0320	09 - 225CDT0058	Cmbnr - WIJD862-10S - S/N / 14660-001	
R5					05 - 225CAP0321	10 - 225CDT0059	TRAK 9100-9 - S/N 2328		
Harris - Mod CNSTL6-MHS		NewMar - Mod / 48-15		MTR2000(T5544) S/N 512CHM0134		M-coupler TDF6491A1-1 S/N 0034139864			
S/N - A04590B1-3		S/N / 0165995		Duplexer (Q2330E) S/N CC36333-1-2		Ferrups (FE7KVA) - FE7K03265			

Deschutes County Sheriff's Office
TeNSr Channel Bank Configurations



Chn Bnk		Spring River Butte				Chassis Model/Serial/Rev:							
7						891830 / 015367 / B1							
F R O N T		Card Slot Module				Plug-In							
	Card Slot	Part No.	Serial No.	Description	Fimware/Board Ver	1				2			
						Part No.	Serial	Item	Version	Part No.	Serial	Item	Version
	C1	8800	013278	CPU-3 BCON	F 3.9.0 / Rev D2-0								
	C2												
	P1												
	P2												
	P3												
	W1	801060	037334	WAN DUAL	Rev E4-0			DSX				DSX	
	W2												
W3													
W4													
F1	8901		POWER SUPPLY, AC		Lat: N 43 52 25.8				Elev. 1487 m				
F2	8901		POWER SUPPLY, AC		Lon: W 121 30 17.0				4879 ft				
B A C K		Card Slot Module				Plug-In							
	Card Slot	Part No.	Serial No.	Description	Firmware/Board Ver	Part No.	Serial	Item	Version				
	IF	892360	008558	INF+M T1E1*8	B0-0								
	U1	816460	003784	DSM-II 4W*4 FRED	Rev F3-0 / V 2.9	864		FRED					
	U2	816460	003415	DSM-II 4W*4	Rev F3-0 / V 2.9								
	U3	816460	009288	DSM-II 4W*4	Rev F3-0 / V 2.9								
	U4												
	U5												
	U6	812960	046439	FXS 2W*8	Rev C1-0								
	U7	811960	024009	E&M 4W*8ER	Rev F2-0								
	U8	822560	003300	SRU-LD 232*10	Rev A0-0 / V 1.2								
	R1					01 - 225CAP0322	06 - 225CDT0061	RESC - MTC 3600 - KV285					
	R2					02 - 225CAP0323	07 - 225CDT0062	TX-RX Filter Mod 89-86A-01349					
	R3					03 - 225CAP0324	08 - 225CDT0063	S/N 58724-A2					
	R4					04 - 225CAP0325	09 - 225CDT0064	Cmbnr - WIJD862-10S - S/N / 14660-001					
R5					05 - 225CAP0326	10 - 225CDT0065	TRAK 9100-9 - S/N 2332						
						M-coupler TDF6491A1-1 S/N 0034139864							
						Ferrups (FE7KVA) - FE7K03265							

Deschutes County Sheriff's Office
TeNSr Channel Bank Configurations



Chn Bnk		Wampus Butte				Chassis Model/Serial/Rev:							
8						891823 / 003414 / A1							
F R O N T	Card Slot	Card Slot Module				Plug-In							
	Card Slot	Part No.	Serial No.	Description	Firmware/Board Ver	1				2			
	Part No.	Serial	Item	Version	Part No.	Serial	Item	Version	Part No.	Serial	Item	Version	
	C1	8802	014998	CPU-3 BCON	F3.9.0 / Rev D2-0								
	C2												
	P1												
	P2												
	P3												
	W1	801060	010430	WAN DUAL	Rev E3-0			DSX				DSX	
	W2												
W3													
W4													
F1	8901		POWER SUPPLY, AC		Lat: N 43 41 58.9				Elev. 1519 m				
F2	8901		POWER SUPPLY, AC		Lon: W 121 37 19.0				4984 ft				
B A C K	Card Slot	Card Slot Module				Plug-In							
	Card Slot	Part No.	Serial No.	Description	Firmware/Board Ver	Part No.	Serial	Item	Version	Part No.	Serial	Item	Version
	IF	892360	000637	INF+M T1E1*8	Rev A1-0								
	U1	816460	004465	DSM-II 4W*4 FRED	Rev C9-0 / V 2.9	864		FRED					
	U2	816460	005094	DSM-II 4W*4	Rev C9-0 / V 2.9								
	U3	816460	009281	DSM-II 4W*4	Rev F3-0 / V 2.9								
	U4												
	U5												
	U6	812960	046436	FXS 2W*8-6	Rev C1-0								
	U7	811960	011656	E&M 4W*8ER	Rev F2-0								
	U8	822560	003297	SRU-LD 232*10	Rev A0-0 / V 1.2								
	R1					01 - 225CDT0040	06 - 225CDT0045	RESC - MTC 3600 - ?????					
	R2					02 - 225CDT0041	07 - 225CDT0046	TX-RX Filter Mod 89-86A-01349					
	R3					03 - 225CDT0042	08 - 225CDT0047	S/N 58724-A2					
	R4					04 - 225CDT0043	09 - 225CDT0048	Cmbnr - WIJD862-10S S/N - 14657-001					
R5					05 - 225CDT0044	10 - 225CDT0049	TRAK 9100-9 - S/N 2329						
							Multicoupler - S/N - 3-16833-F						

Deschutes County Sheriff's Office
TeNSr Channel Bank Configurations



Chn Bnk 9Mount Bachelor - Pine Marten 9-18-08					Chassis Model/Serial/Rev: 891830 / 046927 /B2								
FRONT	Card Slot	Card Slot Module				Plug-In							
	Card Slot	Part No.	Serial No.	Description	Fimware/Board Ver	1				2			
	Part No.	Serial	Item	Version	Part No.	Serial	Item	Version	Part No.	Serial	Item	Version	
	C1	880460	08942	CPU-RCON	V 3.9.3 / Rev D1-0								
	C2												
	P1												
	P2												
	P3												
	W1	801060	012473	WAN DUAL SS	Rev F0-0			DSX				DSX	
	W2												
W3													
W4													
F1	8901		POWER SUPPLY, AC		Lat: N 43 59 26.4				Elev. 2360 m				
F2	8901		POWER SUPPLY, AC		Lon: W 121 41 11.5				7743 Ft				
BACK	Card Slot	Card Slot Module				Plug-In							
	Card Slot	Part No.	Serial No.	Description	Firmware/Board Ver	Part No.	Serial	Item	Version	Part No.	Serial	Item	Version
	IF	892360	020108	INF+M T1E1*8	Rev C0-0								
	U1	816460	014987	DSM-II 4W*4	Rev F3-0 Ver 2.9								
	U2	816460	011550	DSM-II 4W*4	Rev F3-0 Ver 2.9	864							
	U3	816460	014984	DSM-II 4W*4	Rev F3-0 Ver 2.9								
	U4												
	U5												
	U6	812960	045356	FXS 2W*8-6	Rev C1-0								
	U7	811960	036221	E&M 4W*8ER	Rev F2-0								
	U8	822560	009391	SRU-LD 232*10	Rev A1-0 / Ver 1.2								
	R1	8906		RING GENERATOR		01 - 225CJK0081	06 - 225CJK0075	RESC - MTC 3600 - KV434					
	R2					02 - 225CJK0082	07 - 225CJK0077	TX-RX Filter Mod 89-86A-01349					
	R3					03 - 225CJK0083	08 - 225CJK0078	S/N 58724-A2					
	R4					04 - 225CJK0076	09 - 225CJK0079	Cmbnr - WIJD862-10S - S/N / 14660-001					
R5	8903		48VDC CONVERTER		05 - 225CJK0074	10 - 225CJK0080	TRAK 9100-9 - S/N ????						
					M-coupler TDF6491A1-1 S/N 0034139864								
					Eaton (9170+) - EB203T0005								

Deschutes County Sheriff's Office
TeNSr Channel Bank Configurations



Chn Bnk		Antelope Butte				Chassis Model/Serial/Rev:								
10						891830 / 21353 /								
F R O N T		Card Slot Module				Plug-In								
	Card Slot	Part No.	Serial No.	Description	Fimware/Board Ver	1				2				
						Part No.	Serial	Item	Version	Part No.	Serial	Item	Version	
	C1	880460	005593	CPU-RCON	Rev C1-0, Ver 3.9.3									
	C2													
	P1													
	P2													
	P3													
	W1	801060	058997	WAN DUAL SS	Rev E4	811	059546	DSX		811	059620	DSX		
	W2													
W3														
W4														
F1	8901	036764	POWER SUPPLY, AC		Lat = N 43 48 41.8				Elev 1858m					
F2	8901	036735	POWER SUPPLY, AC		Lon: W 120 52 27.9				6096 ft					
B A C K		Card Slot Module				Plug-In								
	Card Slot	Part No.	Serial No.	Description	Firmware/Board Ver	Part No.		Serial		Item		Version		
	IF	892360	015024	INTF+Modem T1E1*8	Rev B0-0									
	U1	816460	009297	DSM-II 4W*4 FRED	Rev F3-0 / V 2.9	864		002691		FRED				
	U2	816460	001458	DSM-II 4W*4	Rev F3-0 / V 2.9									
	U3	816460	003831	DSM-II 4W*4	Rev F3-0 / V 2.9									
	U4													
	U5													
	U6	812960	040543	FXS 2W*8-6	Rev C1-0									
	U7	811960	023683	E&M 4W*8ER	Rev F2-0									
	U8	822560	003248	SRU-LD 232*10	Rev A0-0 / V 1.2									
	R1	8906		RING GENERATOR		01 - 225CDT0040	06 - 225CDT0045	RESC - MTC 3600 - 377CGT0009						
	R2					02 - 225CDT0041	07 - 225CDT0046	TX-RX Filter Mod 89-86A-01349						
	R3					03 - 225CDT0042	08 - 225CDT0047	S/N 58724-A2						
	R4					04 - 225CDT0043	09 - 225CDT0048	Cmbnr-WIJD862-10S - S/N - 14657-001						
R5	8903		48VDC CONVERTER		05 - 225CDT0044	10 - 225CDT0049	TRAK 9100-9 - S/N 2330							
Stratex - Mod. - RMA-04DS1-2-48					ONAN - Mod. LTB-5618532					Multicoupler - S/N - 3-16833-F				
S/N - GPC1035596					S/N - D030488702									
					Ferrups S/N FE12.5K02917									

Deschutes County Sheriff's Office
TeNSr Channel Bank Configurations



Chn Bnk 11 Hampton Butte - Future Chassis Model/Serial/Rev: 891830 / XXXXXX / XX													
F R O N T	Card Slot	Card Slot Module				Plug-In							
		Part No.	Serial No.	Description	Firmware/Board Ver	1				2			
	C1					Part No.	Serial	Item	Version	Part No.	Serial	Item	Version
	C2												
	P1												
	P2												
	P3												
	W1												
	W2												
	W3												
B A C K	W4												
	F1												
	F2												
	Card Slot	Card Slot Module				Plug-In							
		Part No.	Serial No.	Description	Firmware/Board Ver	Part No.	Serial	Item	Version				
	IF			INF+M T1E1*8									
	U1												
	U2												
	U3												
	U4												
	U5												
	U6												
	U7												
	U8			SRU-LD 232*10									
	R1												
	R2												
	R3												
	R4												
	R5												

Deschutes County Sheriff's Office
TeNSr Channel Bank Configurations



Chn Bnk		Awbrey Butte - Microwave to DCSO				Chassis Model/Serial/Rev:							
12						891823 / 003417 / A1							
F R O N T	Card Slot	Card Slot Module				Plug-In							
	Card Slot	Part No.	Serial No.	Description	Firmware/Board Ver	1				2			
						Part No.	Serial	Item	Version	Part No.	Serial	Item	Version
	C1	880360	009625	CPU-5 XCON	FW5.3.0,KER5.0.1,REVB0								
	C2	880360	009672	CPU-5 XCON	FW5.3.0,KER5.0.1,REVB0								
	P1												
	P2												
	P3												
	W1	801060	0096202	WAN DUAL	Rev E2	811	007487	DSX	Rev F0	811	036771	DSX	Rev F0
	W2												
	W3												
	W4	8014	001432	WAN-R DUAL	Rev D4	811	008112	DSX	Rev F0	811	008125	DSX	Rev F0
B A C K	F1	8901	031529	POWER SUPPLY, AC	Rev H9								
	F2	8901	028631	POWER SUPPLY, AC	Rev H9								
	Card Slot	Card Slot Module				Plug-In							
	Card Slot	Part No.	Serial No.	Description	Firmware/Board Ver	Part No.	Serial	Item	Version				
	IF	892360	014580	INF+M T1E1*8	Rev C0-0								
	U1												
	U2	811960	023733	E&M 4W*8	Rev F2								
	U3	811960	036359	E&M 4W*8	Rev F2								
	U4	811960		E&M 4W*8									
	U5												
	U6	810860	002116	E&M 2W*8	Rev A5								
	U7												
	U8	822560	002363	SRU-LD 232*10	Fw1.2,Ker1.0,RevA1								
	R1												
	R2												
	R3												
	R4												
	R5												

Deschutes County Sheriff's Office
TeNSr Channel Bank Configurations



Chn Bnk		DCSO 911 Equipment Room - Microwave to Awbrey				Chassis Model/Serial/Rev:							
13						891823 / 003509 / A1							
F R O N T	Card Slot	Card Slot Module				Plug-In							
	Card Slot	Part No.	Serial No.	Description	Firmware/Board Ver	1				2			
	Part No.	Serial	Item	Version	Part No.	Serial	Item	Version					
	C1	880360	002064	CPU-5 XCON	CPU 5.0.0,Ker 5.0.0, Rev A0								
	C2	880360	002022	CPU-5 XCON	CPU 5.0.0,Ker 5.0.0, Rev A0								
	P1												
	P2												
	P3												
	W1	801060	036245	WAN DUAL	Rev E4	81130	031328	DSX	A1	81130	031545	DSX	A1
	W2												
W3													
W4	801460	000245	WAN-R DUAL	Rev E1	811	036777	DSX	F0	811	036747	DSX	F0	
F1	8901	031547	POWER SUPPLY, AC	Rev H9									
F2	8901	043626	POWER SUPPLY, AC	Rev H9									
B A C K	Card Slot	Card Slot Module				Plug-In							
	Card Slot	Part No.	Serial No.	Description	Firmware/Board Ver	Part No.	Serial	Item	Version				
	IF	892360	001794	INF+M T1E1*8	Rev A1								
	U1												
	U2	811960	024021	E&M 4W*8	Rev F2								
	U3	811960	024006	E&M 4W*8	Rev F2								
	U4	811960	024013	E&M 4W*8	Rev F2								
	U5												
	U6	810860	001740	E&M 2W*8	A5								
	U7												
	U8	822560	003342	SRU-LD 232*10	Fw 1.2, KER 1.0, Rev B2								
	R1												
	R2												
	R3												
	R4												
R5													

**Awbrey
Butte**

LINE	ASSET #	MANUFACTURER	SERIAL #	MODEL	DESCRIPTION	RACK #	QTY
1	006635	Best Power			Uninterruptible power supply UPS	1	
2	012367		Q0429069		Propane tank - 1000gals A/G Trinity		
3	009510				Fencing wire with razor ribbon wire		
4		Motorola		RNL4924A	Transector Multi-outlet Suppressor	2	
5		Motorola		RNL4924A	Transector Multi-outlet Suppressor	3	
6		Motorola		RNL4924A	Transector Multi-outlet Suppressor	4	
7		Motorola		RNL4924A	Transector Multi-outlet Suppressor	7	
8		Motorola		RMP-620AT	Transector Power Suppressor	12	
9		Motorola		RMP-620AT	Transector Power Suppressor	11	
10		Motorola		RMP-620AT	Transector Power Suppressor	10	
11		Motorola		RMP-620AT	Transector Power Suppressor	9	
12		Motorola		RMP-620AT	Transector Power Suppressor	8	
13		Motorola		RMP-620AT	Transector Power Suppressor	7	
14		Motorola		RMP-620AT	Transector Power Suppressor	6	
15		Motorola		RMP-620AT	Transector Power Suppressor	6	
16		Motorola		RMP-620AT	Transector Power Suppressor	5	
17		Motorola	CM101CWM00 26	K0784D26768	CM6 Microwave to Grey Butte	10	
18		Motorola		IMACS/800	TeNSr/800 channel bank 1	2	
19		Motorola		IMACS/800	TeNSr/800 channel bank 2	2	
20		Motorola		IMACS/800	TeNSr/800 channel bank 3	2	
21		Motorola		IMACS/800	TeNSr/800 channel bank 4	2	
22		Motorola			ADC DS1 Interface 1	2	
23		Motorola			ADC DS1 Interface 2	2	
24		Motorola			ADC DSMII Interface 1	2	
25		Motorola			ADC DSMII Interface 2	2	
26		Motorola			ADC DSMII Interface 3	2	
27		Motorola			ADC DSMII Interface 4	2	
28		Motorola			ADC DSMII Interface 5	2	
29		Motorola			ADC DSMII Interface 6	2	

30		Motorola			ADC DSMII Interface 7	2	
31		Motorola			ADC DSMII Interface 8	2	
32		Motorola			ADC E&M Interface 1	2	
33		Motorola			ADC E&M Interface 2	2	
35		Trak Systems			GPS Reference	3	
36		Ries Labs Inc			Audio Optimization Unit	3	
37	00012585	Black Box			Port Manager	3	
38		Black Box			Secure Site Manager	3	
39		Motorola	276AXC0013	L99ZX+256L	Spectra control station	3	
40	00005024	Motorola	225CXP0177	T5365A	Quantar repeater channel 5	3	
41		Motorola	225CXD0020	T5365A	Quantar repeater channel 4	3	
42		Motorola	225CXD0019	T5365A	Quantar repeater channel 3	3	
43		Motorola	225CDT0060	T5365A	Quantar repeater channel 2	3	
44		Motorola	225CXD0128	T5365A	Quantar repeater channel 1	3	
45		RFS	58724-A3	89-86A-01349	RX Multi-coupler	4	
46		RFS	14661-001	WIJD862-10S	TX Combiner	4	
47		Motorola	225CCT0130	T5365A	Quantar repeater channel 10	4	
48		Motorola	225CCF0129	T5365A	Quantar repeater channel 9	4	
49		Motorola	225CCT0127	T5365A	Quantar repeater channel 8	4	
50		Motorola	225CCT0128	T5365A	Quantar repeater channel 7	4	
51		Motorola	225CCT0131	T5365A	Quantar repeater channel 6	4	
52	00011442	Motorola		CPX2000	MTC3600 Prime Main Controller	6	
53	00011443	Motorola		CPX2000	MTC3600 Prime Alt Controller	6	
54	00011441	Motorola		CPX2000	MTC3600 Resc Controller	6	
56	08386	Motorola	EZ777		RNC PRIME	5	
58	08387	Motorola	EZ778		RNC SPARE	5	
60		Motorola	TPN1217B-002	TPN1217B	Power Supply	8	
61	00007872	Motorola		Q2980A	Digitac Interface #1	8	
62	00007872	Motorola		Q2980A	Digitac Interface #2	8	
63	00007872	Motorola	424CWW0124	Q2980A	Digitac Channel #1	8	
64	00007872	Motorola	424CWW0126	Q2980A	Digitac Channel #3	8	
65	00007872	Motorola	424CWW0125	Q2980A	Digitac Channel #5	8	
66	00007872	Motorola	424CWW0127	Q2980A	Digitac Channel #7	8	
67		Motorola			TIMI Alternative Modem	7	

68		Motorola			TIMI Main	7	
69		Black Box			Port Master Modem 541-385-1768	7	
70		Motorola			UDS Modem (not used)	7	
71		Variswitch			Series 5800 T-Bar Power Alarm	7	
72	00007872	Variswitch			T-Bar Data Switch	7	
73		Vega	5013	225-M		7	
74	00007872	Motorola			Digitac USCI Interface #1	7	
75	00007872	Motorola			Digitac USCI Interface #2	7	
76	00007872	ADC			Cat 5E Cross Connect	7	
77		Motorola			USCI #1	7	
78		Motorola			USCI #2	7	
79		LTO			Audio Compressor Limiter #1	7	
80		LTO			Audio Compressor Limiter #2	7	
81		LTO			Audio Compressor Limiter #3	7	
82		LTO			Audio Compressor Limiter #4	7	
84		Motorola			MC3000 Remote Deskset	9	
85		Motorola	TPN1217B-003	TPN1217B	Power Supply	9	
86		Motorola			Console/Deskset Interface	9	
87	00007872	Motorola			Digitac Interface #3	9	
88	00007872	Motorola			Digitac Interface #4	9	
89	00007872	Motorola	424CXP0088	Q2980A	Digitac Channel #2	9	
90	00007872	Motorola	424CAR0014	QLN3380A	Digitac Channel #4	9	
91	00007872	Motorola	424CAR0015	Q2980A	Digitac Channel #6	9	
91	00007872	Motorola	424CAR0016	Q2980A	Digitac Channel #8	9	
93		Motorola	TPN1217B-001	TPN1217B	Power Supply	10	
94	00007872	Motorola			Digitac Interface #5	10	
95	00007872	Motorola	424CAR0018	QLN3380A	Digitac Channel #9	10	
96	00007872	Motorola	424CAR0017	QLN3380A	Digitac Channel #10	10	
97	00007875	Harris			Constellation Microwave	11	
98		Telect				11	
99	00011411	Adtran		Atlas 550	Atlas 550	11	
100		Ibon			Power Sum Cat5	11	
101		FCT			DC Distribution Panel	11	
102		Motorola			UDS Modem	11	

103	00007612	Motorola	680CZF0002		Quantar Data Repeater	11	
104				115-48-30RM	Battery Eliminator/Charger	11	
105		Stratex Networks	GPC1035598	DXRTOP	Microwave to Antelope	12	
106		Stratex Networks	GPC2038301	DXR	Microwave to Antelope	12	
107		Stratex Networks	GPC1035583	DXR	Microwave to Antelope	12	
108		Stratex Networks	GPC4037995	DXP	Microwave to Antelope	12	
109	00011274	Badger		481	Alarm System RS232 Level Converter	12	
110	00011274	Raven			Alarm System Analog FSK Communication Bridge	12	
111	00011274	Badger		481	Alarm System Remote Site Comm Server	12	
112	00011274	Badger			Alarm System Awbrey Site Alarm Monitor #1	12	
113	00011274	Badger			Alarm System - Awbrey Site Alarm Monitor #2	12	
114	00014375	Cisco		3560	Cisco Catalyst 3560 Switch	12	
115		Cisco	FOC1530V3T6	ME-3400	Cisco ME Series Switch	12	
116	00011411	Adtran		Netvanta 8044M	NetVanta 8044M	12	
117		RFS			Receive antenna system		
118		RFS			Transmit antenna system		
119		Motorola	CAF030K99H		Quantar Spare	Spares	
120	00007876	HP	3241A01165	3400B	RMS Voltmeter	Test	1
121	00007876	HP	3621U13304	4934	TIMS	Test	1
122	00007876	HP	3621U13275	4934	TIMS	Test	1
123	00007876	HP		54602B	Oscilloscope	Test	1
124		Motorola			MTC3600 Fan Assy	Spares	3
125		Motorola			UDS Modem v.3400	Spares	2
126		Black Box			MD1000C V3600 Modem	Spares	1
127		Motorola			RIC	Spares	1
128		Motorola			MCPN750 7400616	Spares	1
129		Motorola			PAR (CSC)	Spares	1
130		Motorola			NPAM	Spares	1
131		Motorola	501184		CPCI CSC CPU Main Codeplug?	Spares	1
132		Black Box		RM217	Filler Panels	Spares	6
133		Motorola		TPN1217B	Power Supply	Spares	2

134	07296	Adtran	AWD07A3711	Atlas 550		Spares	1
135	00011411	Adtran	WB0508494	Atlas 550		Spares	1
136	00011411	Adtran	AWD07A3817	Atlas 550		Spares	1
137		Motorola			Quantar Receiver	Spares	1
138		Motorola			Quantar Exciter	Spares	1
139		Motorola			Quantar 100W PA	Spares	1
140		Motorola			Quantar Power Supply	Spares	1
141		Motorola			CPU-XCON TeNSr Spare	Spares	2
142		Motorola			INTFM TeNSr Spare	Spares	3
143		Motorola			CPU-BCON TeNSr Spare	Spares	1
144		Motorola			WAN Dual TeNSr spare	Spares	5
145		Motorola			DSM TeNSr Spare	Spares	1
146		Motorola			FXS TeNSr Spare	Spares	1
147		Motorola			IMACS Ringer	Spares	1
148		Motorola			FRED	Spares	3
149		Motorola			Distribution Module	Spares	1
150		Motorola			False Sense Unit	Spares	1
151		Motorola			48V Power Supply	Spares	1
152		Trak Systems			Trak GPS RS422 Card	Spares	1
153		Trak Systems			GPS AC/DC Power Supply	Spares	1
154		Motorola		6809	Power Supply	Spares	
155		Motorola		9637	T-Bar Control Module	Spares	2
156		Motorola		QRN4515A	Digitac Parts	Spares	1
157		Motorola		QRN4306B39	Digitac Parts	Spares	1
158		Motorola		4516B39	Digitac Parts	Spares	1
159		Motorola		QRN4304C24	Digitac Parts	Spares	1
160		Motorola		QRN3407B39	Digitac Parts	Spares	1
161		Motorola		QRN4305B38	Digitac Parts	Spares	1
162		Best Power			UPS Old From Wampus Butte	Spares	1
163					Equipment racks - all sites and spares		45
164					Radio building on Awbrey Butte - CMU construction		
165		Onan	C040621810	GCFE	Generator on Awbrey Butte		
166					Site fencing		

167		Andrews	9612MRH395A	MRH-052-101	Dry air compressor	10	
168		Sabre	04-11175		Sabre 60' tower		1

Wampus Butte

1	00014413	Daniels	205531	PSA-12A09-PB-00	VHF Repeater M4	5	
2		RFS			Receive Multicoupler	1	
3		RFS	14658-001	WIJD862-10S	Transmit Combiner	1	
4		Adtran			Microwave to T1 Converter for TeNSr	1	
5	00005034	Motorola		RNL4924A	Transector Multi-outlet Suppressor	2	
6		Trak Systems			GPS Reference Receiver	2	
7		Motorola			E & M Interface #1	2	
8		Motorola			DSI Interface #1	2	
9		Motorola			DSM Interface #1	2	
10		Motorola			Port Manager	2	
11	00005033	Motorola	225CXP0179	T5365A	Quantar repeater channel 5	2	
12		Motorola	225CXD0029	T5365A	Quantar repeater channel 4	2	
13		Motorola	225CXD0028	T5365A	Quantar repeater channel 3	2	
14		Motorola	225CXD0027	T5365A	Quantar repeater channel 2	2	
15		Motorola	225CXD0026	T5365A	Quantar repeater channel 1	2	
16		Motorola		RNL4924A	Transector Multi-outlet Suppressor	3	
17				PM-48-10	Power Module	3	
18	00011274	Badger			Badger Alarm Panel	3	
19		Motorola	225CDT0070	T5365A	Quantar repeater channel 10	3	
20		Motorola	225CDT0099	T5365A	Quantar repeater channel 9	3	

21		Motorola	225CDT0068	T5365A	Quantar repeater channel 8	3	
22		Motorola	225CDT0067	T5365A	Quantar repeater channel 7	3	
23		Motorola		T5365A	Quantar repeater channel 6	3	
24	00011437	Motorola		CPX2000	MTC3600 Prime Remote Site Controller	4	
25	00007613	Motorola	680CZF0001		Quantar Data Repeater	4	
26		Eaton			UPS	6	
27		RFS			Receive antenna system		
28		RFS			Transmit antenna system		

Antelope Butte

1	00011439	Motorola	KV202	76406A	MTC3600 Prime Remote Site Controller	1	
2		Motorola		RNL4924A	Transector Multi-outlet Suppressor	2	
3		Trak Systems			GPS Reference Receiver	2	
4		Motorola			4 Wire E & M Interface #1	2	
5		Motorola			T1/E1 Interface #1	2	
6		Motorola			DSM II Interface #1	2	
7		Black Box		746-5500	Port Manager	2	
8	00011274	Badger		481	Badger Alarm Panel	2	
9		Motorola			TeNSr/800 channel bank	2	
10		Motorola	225CDT0044	T5365A	Quantar repeater channel 5	2	
11		Motorola	225CDT0043	T5365A	Quantar repeater channel 4	2	
12		Motorola	225CDT0042	T5365A	Quantar repeater channel 3	2	
13		Motorola	225CDT0041	T5365A	Quantar repeater channel 2	2	
14		Motorola	225CDT0040	T5365A	Quantar repeater channel 1	2	
15		Motorola		RNL4924A	Transector Multi-outlet Suppressor	3	
16		RFS	61045-A	DDF1007A	Receive Multicoupler	3	
17		RFS	14657-001	CD860-C	Transmit Combiner	3	
18		RFS		DDF100A	Pre Amp	3	

19		Motorola	225CDT0049	T5365A	Quantar repeater channel 10	3	
20		Motorola	225CDT0048	T5365A	Quantar repeater channel 9	3	
21		Motorola	225CDT0047	T5365A	Quantar repeater channel 8	3	
22		Motorola	225CDT0046	T5365A	Quantar repeater channel 7	3	
23		Motorola	225CDT0046	T5365A	Quantar repeater channel 6	3	
24		Motorola			Transector Multi-outlet Suppressor	4	
25		Stratex Networks			Stratex Microwave	4	
26		Newmar			Power Module	4	
27		Best Power	FE12-5K02917		UPS		
28		Best Power			Transfer Switch		
29					Temp Alert		
30		Onan			Bypass Switch		
31		Motorola			Transector Apex Surge Suppressor		
32			100637		Propane tank		
33		Onan	11961551	8405-209	Generator		
34	00009518				Equipment Shelter pre-fab		
35					Receive antenna system		
36					Transmit antenna system		

**Pine
Martin**

1	00011440	Motorola		76406A	MTC3600 Prime Remote Site Controller	1	
2	00012532	Motorola		RNL4924A	Transector Multi-outlet Suppressor	2	
3	00012532	Trak Systems			GPS Reference Receiver	2	
4	00012532	Motorola			4 Wire E & M Interface #1	2	
5	00012532	Motorola			T1/E1 Interface #1	2	
6	00012532	Motorola			DSM II Interface #1	2	

7	00012532	Black Box		746-5500	Port Manager	2	
8	00012532	Badger		481	Badger Alarm Panel	2	
9	00012532	Motorola			TeNSr/800 channel bank	2	
10	00012532	Motorola	225CKJ0074	T5365A	Quantar repeater channel 5	2	
11	00012532	Motorola	225CKJ0076	T5365A	Quantar repeater channel 4	2	
12	00012532	Motorola	225CKJ0083	T5365A	Quantar repeater channel 3	2	
13	00012532	Motorola	225CKJ0082	T5365A	Quantar repeater channel 2	2	
14	00012532	Motorola	225CKJ0081	T5365A	Quantar repeater channel 1	2	
15	00012532	Motorola		RNL4924A	Transector Multi-outlet Suppressor	3	
16	00012532	RFS		DDF1007A	Receive Multicoupler	3	
17	00012532	RFS		CD860-C	Transmit Combiner	3	
18	00012532	RFS		DDF100A	Pre Amp	3	
19	00012532	Motorola	225CKJ0080	T5365A	Quantar repeater channel 10	3	
20	00012532	Motorola	225CKJ0079	T5365A	Quantar repeater channel 9	3	
21	00012532	Motorola	225CKJ0078	T5365A	Quantar repeater channel 8	3	
22	00012532	Motorola	225CKJ0077	T5365A	Quantar repeater channel 7	3	
23	00012532	Motorola	225CKJ0075	T5365A	Quantar repeater channel 6	3	
24	00012532	Motorola			Transector Multi-outlet Suppressor	4	
25	00012532	RFS			Receive antenna system		
26	00012532	RFS			Transmit antenna system		
27	00012532	Eaton			UPS	5	

1	00007873	Motorola		76406A	MTC3600 Prime Remote Site Controller	3	
2		Motorola		RNL4924A	Transector Multi-outlet Suppressor	2	
3	00007873	Trak Systems			GPS Reference Receiver	2	
4		Motorola			4 Wire E & M Interface #1	2	
5		Motorola			T1/E1 Interface #1	2	
6		Motorola			DSM II Interface #1	2	
7		Black Box		746-5500	Port Manager	2	
8	00011274	Badger		481	Badger Alarm Panel	2	
9	00007873	Motorola			TeNSr/800 channel bank	2	
10	00007873	Motorola	255CAP0321	T5365A	Quantar repeater channel 5	2	
11	00007873	Motorola	255CAP0320	T5365A	Quantar repeater channel 4	2	
12	00007873	Motorola	255CAP0319	T5365A	Quantar repeater channel 3	2	
13	00007873	Motorola	255CAP0318	T5365A	Quantar repeater channel 2	2	
14	00007873	Motorola	255CAP0317	T5365A	Quantar repeater channel 1	2	
15		Motorola		RNL4924A	Transector Multi-outlet Suppressor	1	
16		RFS		DDF1007A	Receive Multicoupler	1	
17		RFS	294127-001	CD860-C	Transmit Combiner	1	
18		RFS		DDF100A	Pre Amp	1	
19		Motorola	255CDT0059	T5365A	Quantar repeater channel 10	3	
20		Motorola	255CDT0058	T5365A	Quantar repeater channel 9	3	
21		Motorola	255CDT0057	T5365A	Quantar repeater channel 8	3	
22		Motorola	255CDT0056	T5365A	Quantar repeater channel 7	3	
23		Motorola	255CDT0055	T5365A	Quantar repeater channel 6	3	
24		Motorola			Transector Multi-outlet Suppressor	3	
25		Newmar			Power Module	4	
26		Best Power			UPS	5	
27	00007873	RFS			Receive antennas system		
28	00007873	RFS			Transmit antenna system		
29							
30		Andrew	9612MRH396A	MRH-052-101	Dry air compressor	4	
31	00007873	Motorola	680CKD0002	T5365A	Quantar data repaeter	1	
32		Motorola	512CHM0134	T5544A	MTR2000 VHF repeater	4	
33					Duplexer	4	
34					VHF antenna system		

35	00007873	Harris			Harris microwave	4	
36	00007873				Equipment racks and grounding		

**Spring
River
Butte**

1	00007874	Motorola		76406A	MTC3600 Prime Remote Site Controller	1	
2	00007874	Motorola		RNL4924A	Transector Multi-outlet Suppressor	1	
3	00007874	Trak Systems			GPS Reference Receiver	1	
4		Motorola			4 Wire E & M Interface #1	2	
5		Motorola			T1/E1 Interface #1	2	
6		Motorola			DSM II Interface #1	2	
7		Black Box		746-5500	Port Manager	2	
8		Badger		481	Badger Alarm Panel	3	
9		Motorola			TeNSr/800 channel bank	2	
10	00007874	Motorola	255CAP0326	T5365A	Quantar repeater channel 5	2	
11	00007874	Motorola	255CAP0325	T5365A	Quantar repeater channel 4	2	
12	00007874	Motorola	255CAP0324	T5365A	Quantar repeater channel 3	2	
13	00007874	Motorola	255CAP0323	T5365A	Quantar repeater channel 2	2	
14	00007874	Motorola	255CAP0322	T5365A	Quantar repeater channel 1	2	
15		Motorola		RNL4924A	Transector Multi-outlet Suppressor	2	
16		RFS		DDF1007A	Receive Multicoupler	1	
17		RFS		CD860-C	Transmit Combiner	1	
18		RFS		DDF100A	Pre Amp	1	
19		Motorola	255CDT0065	T5365A	Quantar repeater channel 10	3	
20		Motorola	255CDT0064	T5365A	Quantar repeater channel 9	3	
21		Motorola	255CDT0063	T5365A	Quantar repeater channel 8	3	

22		Motorola	255CDT0062	T5365A	Quantar repeater channel 7	3	
23		Motorola	255CDT0061	T5365A	Quantar repeater channel 6	3	
24		Motorola			Transector Multi-outlet Suppressor	3	
25		Best Power			UPS	4	
26	07874	RFS			Receive antenna system		
27		RFS			Transmit antenna system		
28	9512				Fencing		

Gray
Butte

1	00011438	Motorola		76406A	MTC3600 Prime Remote Site Controller	3	
2	00005030	Motorola		RNL4924A	Transector Multi-outlet Suppressor	2	
3		Trak Systems			GPS Reference Receiver	2	
4		Motorola			4 Wire E & M Interface #1	2	
5		Motorola			T1/E1 Interface #1	2	
6		Motorola			DSM II Interface #1	2	
7	00005036	Black Box		746-5500	Port Manager	2	
8		Badger		481	Badger Alarm Panel	2	
9		Motorola			TeNSr/800 channel bank	2	
10	00005029	Motorola	255CXP0178	T5365A	Quantar repeater channel 5	3	
11		Motorola	255CXD0025	T5365A	Quantar repeater channel 4	3	
12		Motorola	255CXD0024	T5365A	Quantar repeater channel 3	3	
13		Motorola	255CXD0022	T5365A	Quantar repeater channel 2	3	
14		Motorola	255CXD0021	T5365A	Quantar repeater channel 1	3	

15		Motorola		RNL4924A	Transector Multi-outlet Suppressor	3	
16		RFS	58724-A1	89-86A-01349	Receive Multicoupler	2	
17		RFS	14660-001	WIJD862-10S	Transmit Combiner	2	
18		RFS	7054934-001	WIJD862-10S	Transmit Combiner	2	
19		Motorola	255CDT0054	T5365A	Quantar repeater channel 10	4	
20		Motorola	255CDT0053	T5365A	Quantar repeater channel 9	4	
21		Motorola	255CDT0052	T5365A	Quantar repeater channel 8	4	
22		Motorola	255CDT0051	T5365A	Quantar repeater channel 7	4	
23		Motorola	255CDT0050	T5365A	Quantar repeater channel 6	4	
24		Motorola			Transector Multi-outlet Suppressor	4	
25		Motorola			CM6 Microwave to Grey Butte	1	
26		Newmar			Power Module	4	
27		Best Power			UPS	5	
28	00007614	Motorola	680CZF0003	T5365A	Quantar Data Repeater	4	
29	00009907	Motorola	MTR2000		VHF Repeater	1	
30		Telewave	10861	TPRD-1556	VHF Duplexer	1	
31		Onan			Transfer Switch		
32		Best Power			Bypass Switch		
33		Motorola			Transector Apex Surge Suppressor		
34		RFS			Receive antenna system		
35		RFS			Transmit antenna system		
36		Andrews	9612MRH396A	MRH-052-101	Dry air compressor		

Pine
Mountain

1	00014278	Daniels	200166	PSA-12A09-PB-00	VHF Repeater M4	1	1
2		Telewave	10863	TPRD-1556	Duplexer	1	1
3					Antenna System and tower mounting hardware	1	1

Jack Pine
Ridge

1		Daniels	512CHM0133	T5544A	MTR2000 VHF repeater		1
2		Telewave		TPRD-1556	Duplexer		1
3					Antenna System and tower mounting hardware		1

NW
Express

1	00014279	Daniels	200161	PSA-12A09-PB-00	VHF Repeater M4	1	1
2		Telewave		TPRD-1556	Duplexer	1	1
3					Antenna System and tower mounting hardware	1	1

Spare
Antennas

1		RFS		1109-1	RFS 806-869 antennas		6
2		RFS		620-3N	RFS 150-159 antenna		2

Misc

1	12636	Genesis			Genwatch 3 - software		
---	-------	---------	--	--	-----------------------	--	--