

Deschutes County Sheriff's Office
TeNSr Channel Bank Configurations



Chn Bnk		Awbrey Butte - Prime Site				Chassis Model/Serial/Rev:							
1						891830 / 32732 / B2							
F R O N T	Card Slot	Card Slot Module				Plug-In							
	Card Slot	Part No.	Serial No.	Description	Fimware/Board Ver	1				2			
	Part No.	Serial	Item	Version	Part No.	Serial	Item	Version					
	C1	880360	017870	CPU-5 XCON	V 5.3.1 Ker 5.0.1 / B0-0								
	C2	880360	017879	BACKUP CPU-5 XCON	V 5.3.1 Ker 5.0.1 / B0-0								
	P1												
	P2												
	P3												
	W1	801060	058996	WAN DUAL	E4-0	81130	059547	DSX	A1	81130	059604	DSX	A1
	W2	801060	058995	WAN DUAL	E4-0	81130	059607	DSX	A1	81130	059453	DSX	A1
W3	801060	036432	WAN DUAL	E4-0			DSX				DSX		
W4	801460	002197	WAN-R DUAL	E3-0	81130	031675	DSX	A1	81130	031715	DSX	A1	
F1	8901		POWER SUPPLY, AC		Lat 44-04-38.8 N Elev: 1269 M								
F2	8901		POWER SUPPLY, AC		Lon 121-19-55.1 W 4163 Ft								
B A C K	Card Slot	Card Slot Module				Plug-In							
	Card Slot	Part No.	Serial No.	Description	Firmware/Board Ver	Part No.	Serial	Item	Version				
	IF	892360	009213	INF+M T1E1*8	Rev A1-0								
	U1	816460	009303	DSM4*4	F3-0 / V2.9								
	U2	816460	009289	DSM4*4	F3-0 / V2.9								
	U3	816460	004077	DSM4*4	C9-0 / v2.9								
	U4	816460	003775	DSM4*4	F3-0 / V2.9			Fred					
	U5	816460	003884	DSM4*4	F3-0 / V2.9								
	U6	811960	024015	E&M 4W*8ER	F2-0								
	U7	8139	007987	FXO 2W*8-6	H2-0								
	U8	822560	003250	SRU-LD 232*10	A0-0 / V 1.2								
	R1					01 - 225CXD0128	06 - 225CCT0131	Prime (Mn) MTC3600 377CGT0165					
	R2					02 - 225CXD0018	07 - 225CCT0128	Prime (Bu) MTC3600 377CGT0069					
	R3					03 - 225CXD0019	08 - 225CCT0127	Prime (Re) MTC3600 377CGT0006					
	R4					04 - 225CXD0020	09 - 225CCT0129	CmbLine Fltr - Mod / 89-86A-01349					
R5					05 - 225CXP0177	10 - 225CCT0130	S/N / 58724-A3						
Harris - Mod CNSTL6-MHS		CM - Mod. CM6 - A07HYD2676A		Stratex - Mod - DXR700		DBS (02)-T5365A/680CZF0002-854.9625		Cmbnr-WIJD862-10S S/N 14661-001					
S/N - A04590A1-A1		S/N - CM101CWM0026		S/N - GPC1035596		Ferrups S/N FE18K04923		TRAK 9100-8 S/N 765					
S/N - A04590A1-A2													

Deschutes County Sheriff's Office
TeNSr Channel Bank Configurations



Chn Bnk		Awbrey Butte - Prime Site				Chassis Model/Serial/Rev:							
2						891830 / 32947 / B2							
F R O N T		Card Slot Module				Plug-In							
	Card Slot	Part No.	Serial No.	Description	Firmware/Board Ver	1				2			
		Part No.	Serial	Item	Version	Part No.	Serial	Item	Version				
	C1	880360	017908	CPU-5 XCON	V 5.3.1 Ker 5.0.1 / B0-0								
	C2	880360	017878	BACKUP CPU-5 XCON	V 5.3.1 Ker 5.0.1 / B0-0								
	P1												
	P2												
	P3												
	W1	801060	059532	DSX+DSX WAN DUAL	E4-0	81130	061039	DSX	A1	81130	061053	DSX	A1
	W2												
W3	801060	005128	DSX+DSX WAN DUAL	E3-0	81130	061050	DSX	A1	81130	061058	DSX	A1	
W4													
F1	8901	037168	POWER SUPPLY, AC										
F2	8901	036883	POWER SUPPLY, AC										
B A C K		Card Slot Module				Plug-In							
	Card Slot	Part No.	Serial No.	Description	Firmware/Board Ver	Part No.		Serial		Item		Version	
	IF	892360	009479	INF+M T1E1*8	B1-0 / 2.9								
	U1	8164	002424	DSM-II 4W*4	F3-0 / V2.9								
	U2	8164	001110	DSM-II 4W*4	F3-0 / V2.9								
	U3	8164	009285	DSM-II 4W*4	F3-0 / V2.9	864		002745		FRED		A3	
	U4	8164	002379	DSM-II 4W*4	F3-0 / V2.9								
	U5	8164	000676	DSM-II 4W*4	F3-0 / V2.9								
	U6	811960	036329	E&M 4W *8ER	F2-0								
	U7	8125	000232	FXO 2W*4-6	D1-0								
	U8	822560	003602	SRU-LD 232*10	A0-0 / V 1.2								
	R1					Digitac Comparator							
	R2					01 - 424CWW0124 06 - 424CAR0015							
	R3					02 - 424CXP0088 07 - 424CWW0127							
	R4					03 - 424CWW0126 08 - 424CAR0016							
R5					04 - 424CAR0014 09 - 424CAR0018								
					05 - 424CWW0125 10 - 424CAR0017								

Deschutes County Sheriff's Office
TeNSr Channel Bank Configurations



Chn Bnk		Awbrey Butte - Prime Site				Chassis Model/Serial/Rev: 891830 / 32949 / B2							
3													
F R O N T	Card Slot	Card Slot Module				Plug-In							
	Card Slot	Part No.	Serial No.	Description	Firmware/Board Ver	1				2			
						Part No.	Serial	Item	Version	Part No.	Serial	Item	Version
	C1	880360	017907	CPU-5 XCON Redundant	V 5.3.1 / B0-0								
	C2	880360	017915	CPU-5 XCON	V 5.3.1 / B0-0								
	P1												
	P2												
	P3												
	W1	801060	059529	DSX+DSX WAN DUAL	E4-0	81130	061047	DSX	A1	81130	061041	DSX	A1
	W2	801060	059150	DSX+DSX WAN DUAL	E4-0	81130	059616	DSX	A1	81130	059541	DSX	A1
B A C K	W3	801060	005148	DSX+DSX WAN DUAL	E3-0	81130	061046	DSX	A1	81130	061031	DSX	A1
	W4	801460	005030	WAN-R DUAL	E3-0	81130	059454	DSX	A1	81130	059545	DSX	A1
	F1	8901	037095	POWER SUPPLY, AC									
	F2	8901	037000	POWER SUPPLY, AC									
	Card Slot	Card Slot Module				Plug-In							
	Card Slot	Part No.	Serial No.	Description	Firmware/Board Ver	Part No.				Serial			
	IF	892360	009484	INF+M T1E1*8	B1-0								
	U1	816460	009290	DSM-II 4W*4	Rev F3-0 / V 2.9								
	U2	816460	003861	DSM-II 4W*4	Rev F3-0 / V 2.9								
	U3	816460	009298	DSM-II 4W*4 FRED	Rev F3-0 / V 2.9	864		002713		Fred		A3	
	U4	816460	009274	DSM-II 4W*4	Rev F3-0 / V 2.9								
	U5	816460	003839	DSM-II 4W*4	Rev F3-0 / V 2.9								
	U6	816460	009296	DSM-II 4W*4	Rev F3-0 / V 2.9								
	U7	811960	036342	E&M 4-W*8	Rev F2-0								
	U8	822560	003351	SRU-LD 232*10	Rev A0-0 / V 1.2								
	R1												
	R2												
	R3												
	R4												
	R5												

Deschutes County Sheriff's Office
TeNSr Channel Bank Configurations



Chn Bnk 4					Awbrey Butte - Prime Site								Chassis Model/Serial/Rev: 891830 / 32592 / B2			
F R O N T		Card Slot Module				Plug-In										
	Card Slot	Part No.	Serial No.	Description	Firmware/Board Ver	1				2						
		Part No.	Serial	Item	Version	Part No.	Serial	Item	Version							
	C1	880360	017867	CPU-5 XCON RDNT	5.3.1 / B0-0											
	C2	880360	017876	CPU-5 XCON SSSS	5.3.1 Ker 5.0.1 / B0-0											
	P1															
	P2															
	P3															
	W1	801060	058998	WAN DUAL	Rev E4-0	81130	059614	DSX	A1	81130	059551	DSX	A1			
	W2	801060	059153	WAN DUAL	Rev E4-0	81130	059609	DSX	A1	81130	059611	DSX	A1			
W3	801060	058804	WAN DUAL	Rev E4-0	81130	059542	DSX	A1	81130	059608	DSX	A1				
W4	801460	005023	WAN-R DUAL	Rev E3-0	81130	059580	DSX	A1	81130	059462	DSX	A1				
F1	8901	036526	POWER SUPPLY, AC	H9												
F2	8901	036709	POWER SUPPLY, AC	H9												
B A C K		Card Slot Module				Plug-In										
	Card Slot	Part No.	Serial No.	Description	Firmware/Board Ver	Part No.		Serial		Item		Version				
	IF	892360	001805	INF+M T1E1*8	Rev A1-0											
	U1	816460	009507	DSM-II 4W*4	Rev F3-0 / V 2.9											
	U2	816460	009294	DSM-II 4W*4	Rev F3-0 / V 2.9											
	U3	816460	009271	DSM-II 4W*4 FRED	Rev F3-0 / V 2.9	864		002691		FRED		A3				
	U4	816460	009269	DSM-II 4W*4	Rev F3-0 / V 2.9											
	U5	816460	009280	DSM-II 4W*4	Rev F3-0 / V 2.9											
	U6	811960	011606	E&M 4W*8ER	Rev F2-0											
	U7															
	U8	822560	003330	SRU-LD 232*10	A0-0 / V 1.2											
	R1															
	R2															
	R3															
R4																
R5																

Deschutes County Sheriff's Office
TeNSr Channel Bank Configurations



Chn Bnk 5					Gray Butte								Chassis Model/Serial/Rev: 891823 / 003512 / A1			
F R O N T		Card Slot Module				Plug-In										
	Card Slot	Part No.	Serial No.	Description	Firmware/Board Ver	1				2						
						Part No.	Serial	Item	Version	Part No.	Serial	Item	Version			
	C1	8800	018933	CPU-3 BCON	Rev D2-0 / F 3.9.3											
	C2															
	P1															
	P2															
	P3															
	W1	801060	036410	WAN DUAL	Rev E4-0			DSX				DSX				
	W2															
W3																
W4																
F1	8901		POWER SUPPLY, AC		Lat: N 44 25 06.6 Elev. 1536 m											
F2	8901		POWER SUPPLY, AC		Lon: W 121 06 04.0 5039 ft											
B A C K		Card Slot Module				Plug-In										
	Card Slot	Part No.	Serial No.	Description	Firmware/Board Ver	Part No.		Serial		Item		Version				
	IF	892360	009217	INF+M T1E1*8	Rev B1-0											
	U1	816460	010199	DSM-II 4W*4 FRED	Rev F3-0 / V 2.9	864				FRED						
	U2	816460	010060	DSM-II 4W*4	Rev F3-0 / V 2.9											
	U3	816460	004472	DSM-II 4W*4	Rev C9-0 / V 2.9											
	U4															
	U5															
	U6	8125	000761	FXS 2W *4-6	Rev A3-0											
	U7	811960	011589	E&M 4W*8ER	Rev F2-0											
	U8	822560	003345	SRU-LD 232*10	A0-0 V 1.2											
	R1	8906		RING GENERATOR		01 - 225CXD0021		06 - 225CDT0050		RESC - MTC 3600 - S/N 377CDT0065						
	R2					02 - 225CXD0022		07 - 225CDT0051		TX-RX Filter Mod 89-86A-01349						
	R3					03 - 225CXD0024		08 - 225CDT0052		S/N 58724-A1						
	R4					04 - 225CXD0025		09 - 225CDT0053		Cmbnr-WJD860-S S/N 382434-001						
R5	8903		48VDC CONVERTER		05 - 225CXP0178		10 - 225CDT0054		TRAK 9100-9 S/N 2331							
California Microwave - Mod / CM6, S/N - CM101CWM0027					DBS (03) - 680CZF0003 - 860.9875 S/N 382449-001											

Deschutes County Sheriff's Office
TeNSr Channel Bank Configurations



Chn Bnk		Fivemile Butte				Chassis Model/Serial/Rev:			
6						891830 / 015008 / B1			
F R O N T		Card Slot Module				Plug-In			
	Card Slot	Part No.	Serial No.	Description	Firmware/Board Ver	1		2	
	Part No.	Serial	Item	Version	Part No.	Serial	Item	Version	
	C1	8800	013267	CPU-3 BCON	Rev E0-0 / Ver 3.9.0				
	C2								
	P1								
	P2								
	P3								
	W1	801060	037335	WAN DUAL	Rev E0-0			DSX	
	W2								
W3									
W4									
F1	8901		POWER SUPPLY, AC		Lat: N 44 21 04.3 Elev. 1203 m				
F2	8901		POWER SUPPLY, AC		Lon: W 121 41 28.9 3947 ft				
B A C K		Card Slot Module				Plug-In			
	Card Slot	Part No.	Serial No.	Description	Firmware/Board Ver	Part No.	Serial	Item	Version
	IF	892360	008693	INF+M T1E1*8	Rev B0-0				
	U1	816460	003365	DSM-II 4W*4 FRED	F3-0 / Ver 2.9	864		FRED	
	U2	816460	003363	DSM-II 4W*4	F3-0 / Ver 2.9				
	U3	816460	009425	DSM-II 4W*4	F3-0 / Ver 2.9				
	U4								
	U5								
	U6	812960	046449	FXS 2W*8	Rev C1-0				
	U7	811960	024020	E&M 4W*8ER	Rev F2-0				
	U8	822560	003604	SRU-LD 232*10	Rev A0-0 / Ver 1.2				
	R1					01 - 225CAP0317	06 - 225CDT0055	RESC - MTC 3600 - 377CGT0001	
	R2					02 - 225CAP0318	07 - 225CDT0056	TX-RX Filter Mod 89-86A-01349	
	R3					03 - 225CAP0319	08 - 225CDT0057	S/N 58724-A2	
	R4					04 - 225CAP0320	09 - 225CDT0058	Cmbnr - WIJD862-10S - S/N / 14660-001	
R5					05 - 225CAP0321	10 - 225CDT0059	TRAK 9100-9 - S/N 2328		
		Harris - Mod CNSTL6-MHS		NewMar - Mod / 48-15		MTR2000(T5544) S/N 512CHM0134		M-coupler TDF6491A1-1 S/N 0034139864	
		S/N - A04590B1-3		S/N / 0165995		Duplexer (Q2330E) S/N CC36333-1-2		Ferrups (FE7KVA) - FE7K03265	

Deschutes County Sheriff's Office
TeNSr Channel Bank Configurations



Chn Bnk		Spring River Butte				Chassis Model/Serial/Rev:			
7						891830 / 015367 / B1			
F R O N T		Card Slot Module				Plug-In			
	Card Slot	Part No.	Serial No.	Description	Fimware/Board Ver	1		2	
						Part No.	Serial	Item	Version
	C1	8800	013278	CPU-3 BCON	F 3.9.0 / Rev D2-0				
	C2								
	P1								
	P2								
	P3								
	W1	801060	037334	WAN DUAL	Rev E4-0			DSX	
	W2								
W3									
W4									
F1	8901		POWER SUPPLY, AC		Lat: N 43 52 25.8 Elev. 1487 m				
F2	8901		POWER SUPPLY, AC		Lon: W 121 30 17.0 4879 ft				
B A C K		Card Slot Module				Plug-In			
	Card Slot	Part No.	Serial No.	Description	Firmware/Board Ver	Part No.	Serial	Item	Version
	IF	892360	008558	INF+M T1E1*8	B0-0				
	U1	816460	003784	DSM-II 4W*4 FRED	Rev F3-0 / V 2.9	864		FRED	
	U2	816460	003415	DSM-II 4W*4	Rev F3-0 / V 2.9				
	U3	816460	009288	DSM-II 4W*4	Rev F3-0 / V 2.9				
	U4								
	U5								
	U6	812960	046439	FXS 2W*8	Rev C1-0				
	U7	811960	024009	E&M 4W*8ER	Rev F2-0				
	U8	822560	003300	SRU-LD 232*10	Rev A0-0 / V 1.2				
	R1					01 - 225CAP0322	06 - 225CDT0061	RESC - MTC 3600 - KV285	
	R2					02 - 225CAP0323	07 - 225CDT0062	TX-RX Filter Mod 89-86A-01349	
	R3					03 - 225CAP0324	08 - 225CDT0063	S/N 58724-A2	
	R4					04 - 225CAP0325	09 - 225CDT0064	Cmbnr - WIJD862-10S - S/N / 14660-001	
R5					05 - 225CAP0326	10 - 225CDT0065	TRAK 9100-9 - S/N 2332		
						M-coupler TDF6491A1-1 S/N 0034139864			
						Ferrups (FE7KVA) - FE7K03265			

Deschutes County Sheriff's Office
TeNSr Channel Bank Configurations



Chn Bnk		Wampus Butte				Chassis Model/Serial/Rev:			
8						891823 / 003414 / A1			
F R O N T		Card Slot Module				Plug-In			
	Card Slot	Part No.	Serial No.	Description	Fimware/Board Ver	1		2	
	Part No.	Serial	Item	Version	Part No.	Serial	Item	Version	
	C1	8802	014998	CPU-3 BCON	F3.9.0 / Rev D2-0				
	C2								
	P1								
	P2								
	P3								
	W1	801060	010430	WAN DUAL	Rev E3-0			DSX	
	W2								
W3									
W4									
F1	8901		POWER SUPPLY, AC		Lat: N 43 41 58.9 Elev. 1519 m				
F2	8901		POWER SUPPLY, AC		Lon: W 121 37 19.0 4984 ft				
B A C K		Card Slot Module				Plug-In			
	Card Slot	Part No.	Serial No.	Description	Firmware/Board Ver	Part No.	Serial	Item	Version
	IF	892360	000637	INF+M T1E1*8	Rev A1-0				
	U1	816460	004465	DSM-II 4W*4 FRED	Rev C9-0 / V 2.9	864		FRED	
	U2	816460	005094	DSM-II 4W*4	Rev C9-0 / V 2.9				
	U3	816460	009281	DSM-II 4W*4	Rev F3-0 / V 2.9				
	U4								
	U5								
	U6	812960	046436	FXS 2W*8-6	Rev C1-0				
	U7	811960	011656	E&M 4W*8ER	Rev F2-0				
	U8	822560	003297	SRU-LD 232*10	Rev A0-0 / V 1.2				
	R1					01 - 225CDT0040	06 - 225CDT0045	RESC - MTC 3600 - ?????	
	R2					02 - 225CDT0041	07 - 225CDT0046	TX-RX Filter Mod 89-86A-01349	
	R3					03 - 225CDT0042	08 - 225CDT0047	S/N 58724-A2	
	R4					04 - 225CDT0043	09 - 225CDT0048	Cmbnr - WIJD862-10S S/N - 14657-001	
R5					05 - 225CDT0044	10 - 225CDT0049	TRAK 9100-9 - S/N 2329		
						Multicoupler - S/N - 3-16833-F			

Deschutes County Sheriff's Office
TeNSr Channel Bank Configurations



Chn Bnk		Mount Bachelor - Pine Marten 9-18-08				Chassis Model/Serial/Rev:			
9						891830 / 046927 /B2			
F R O N T		Card Slot Module				Plug-In			
	Card Slot	Part No.	Serial No.	Description	Fimware/Board Ver	1		2	
						Part No.	Serial	Item	Version
	C1	880460	08942	CPU-RCON	V 3.9.3 / Rev D1-0				
	C2								
	P1								
	P2								
	P3								
	W1	801060	012473	WAN DUAL SS	Rev F0-0			DSX	
	W2								
W3									
W4									
F1	8901		POWER SUPPLY, AC		Lat: N 43 59 26.4 Elev. 2360 m				
F2	8901		POWER SUPPLY, AC		Lon: W 121 41 11.5 7743 Ft				
B A C K		Card Slot Module				Plug-In			
	Card Slot	Part No.	Serial No.	Description	Firmware/Board Ver	Part No.	Serial	Item	Version
	IF	892360	020108	INF+M T1E1*8	Rev C0-0				
	U1	816460	014987	DSM-II 4W*4	Rev F3-0 Ver 2.9				
	U2	816460	011550	DSM-II 4W*4	Rev F3-0 Ver 2.9	864			
	U3	816460	014984	DSM-II 4W*4	Rev F3-0 Ver 2.9				
	U4								
	U5								
	U6	812960	045356	FXS 2W*8-6	Rev C1-0				
	U7	811960	036221	E&M 4W*8ER	Rev F2-0				
	U8	822560	009391	SRU-LD 232*10	Rev A1-0 / Ver 1.2				
	R1	8906		RING GENERATOR		01 - 225CJK0081	06 - 225CJK0075	RESC - MTC 3600 - KV434	
	R2					02 - 225CJK0082	07 - 225CJK0077	TX-RX Filter Mod 89-86A-01349	
	R3					03 - 225CJK0083	08 - 225CJK0078	S/N 58724-A2	
	R4					04 - 225CJK0076	09 - 225CJK0079	Cmbnr - WIJD862-10S - S/N / 14660-001	
R5	8903		48VDC CONVERTER		05 - 225CJK0074	10 - 225CJK0080	TRAK 9100-9 - S/N ????		
						M-coupler TDF6491A1-1 S/N 0034139864			
						Eaton (9170+) - EB203T0005			

Deschutes County Sheriff's Office
TeNSr Channel Bank Configurations



Chn Bnk		Antelope Butte				Chassis Model/Serial/Rev:			
10						891830 / 21353 /			
F R O N T		Card Slot Module				Plug-In			
	Card Slot	Part No.	Serial No.	Description	Firmware/Board Ver	1		2	
	Part No.	Serial	Item	Version	Part No.	Serial	Item	Version	
	C1	880460	005593	CPU-RCON	Rev C1-0, Ver 3.9.3				
	C2								
	P1								
	P2								
	P3								
	W1	801060	058997	WAN DUAL SS	Rev E4	811	059546	DSX	811 059620 DSX
	W2								
W3									
W4									
F1	8901	036764	POWER SUPPLY, AC		Lat = N 43 48 41.8		Elev 1858m		
F2	8901	036735	POWER SUPPLY, AC		Lon: W 120 52 27.9		6096 ft		
B A C K		Card Slot Module				Plug-In			
	Card Slot	Part No.	Serial No.	Description	Firmware/Board Ver	Part No.	Serial	Item	Version
	IF	892360	015024	INTF+Modem T1E1*8	Rev B0-0				
	U1	816460	009297	DSM-II 4W*4 FRED	Rev F3-0 / V 2.9	864	002691	FRED	
	U2	816460	001458	DSM-II 4W*4	Rev F3-0 / V 2.9				
	U3	816460	003831	DSM-II 4W*4	Rev F3-0 / V 2.9				
	U4								
	U5								
	U6	812960	040543	FXS 2W*8-6	Rev C1-0				
	U7	811960	023683	E&M 4W*8ER	Rev F2-0				
	U8	822560	003248	SRU-LD 232*10	Rev A0-0 / V 1.2				
	R1	8906		RING GENERATOR		01 - 225CDT0040	06 - 225CDT0045	RESC - MTC 3600 - 377CGT0009	
	R2					02 - 225CDT0041	07 - 225CDT0046	TX-RX Filter Mod 89-86A-01349	
	R3					03 - 225CDT0042	08 - 225CDT0047	S/N 58724-A2	
	R4					04 - 225CDT0043	09 - 225CDT0048	Cmbnr-WIJD862-10S - S/N - 14657-001	
R5	8903		48VDC CONVERTER		05 - 225CDT0044	10 - 225CDT0049	TRAK 9100-9 - S/N 2330		
Stratex - Mod. - RMA-04DS1-2-48					ONAN - Mod. LTB-5618532				
S/N - GPC1035596					S/N - D030488702				
					Ferrups S/N FE12.5K02917				
					Multicoupler - S/N - 3-16833-F				

Deschutes County Sheriff's Office
TeNSr Channel Bank Configurations



Chn Bnk		Hampton Butte - <i>Future</i>										Chassis Model/Serial/Rev:			
11												891830 / XXXXXX / XX			
F R O N T		Card Slot Module				Plug-In									
	Card Slot	Part No.	Serial No.	Description	Fimware/Board Ver	1				2					
						Part No.	Serial	Item	Version	Part No.	Serial	Item	Version		
	C1														
	C2														
	P1														
	P2														
	P3														
	W1														
	W2														
W3															
W4															
F1															
F2															
B A C K		Card Slot Module				Plug-In									
	Card Slot	Part No.	Serial No.	Description	Firmware/Board Ver	Part No.	Serial	Item	Version						
	IF			INF+M T1E1*8											
	U1														
	U2														
	U3														
	U4														
	U5														
	U6														
	U7														
	U8			SRU-LD 232*10											
	R1														
	R2														
	R3														
	R4														
R5															

Deschutes County Sheriff's Office
TeNSr Channel Bank Configurations



Chn Bnk		Awbrey Butte - Microwave to DCSO				Chassis Model/Serial/Rev:							
12						891823 / 003417 / A1							
F R O N T	Card Slot	Card Slot Module				Plug-In							
	Card Slot	Part No.	Serial No.	Description	Firmware/Board Ver	1				2			
						Part No.	Serial	Item	Version	Part No.	Serial	Item	Version
	C1	880360	009625	CPU-5 XCON	FW5.3.0,KER5.0.1,REVB0								
	C2	880360	009672	CPU-5 XCON	FW5.3.0,KER5.0.1,REVB0								
	P1												
	P2												
	P3												
	W1	801060	0096202	WAN DUAL	Rev E2	811	007487	DSX	Rev F0	811	036771	DSX	Rev F0
	W2												
	W3												
	W4	8014	001432	WAN-R DUAL	Rev D4	811	008112	DSX	Rev F0	811	008125	DSX	Rev F0
B A C K	F1	8901	031529	POWER SUPPLY, AC	Rev H9								
	F2	8901	028631	POWER SUPPLY, AC	Rev H9								
	Card Slot	Card Slot Module				Plug-In							
	Card Slot	Part No.	Serial No.	Description	Firmware/Board Ver	Part No.	Serial	Item	Version				
	IF	892360	014580	INF+M T1E1*8	Rev C0-0								
	U1												
	U2	811960	023733	E&M 4W*8	Rev F2								
	U3	811960	036359	E&M 4W*8	Rev F2								
	U4	811960		E&M 4W*8									
	U5												
	U6	810860	002116	E&M 2W*8	Rev A5								
	U7												
	U8	822560	002363	SRU-LD 232*10	Fw1.2,Ker1.0,RevA1								
	R1												
	R2												
	R3												
	R4												
	R5												

Deschutes County Sheriff's Office
TeNSr Channel Bank Configurations



Chn Bnk		DCSO 911 Equipment Room - Microwave to Awbrey				Chassis Model/Serial/Rev:							
13						891823 / 003509 / A1							
F R O N T		Card Slot Module				Plug-In							
	Card Slot	Part No.	Serial No.	Description	Firmware/Board Ver	1				2			
						Part No.	Serial	Item	Version	Part No.	Serial	Item	Version
	C1	880360	002064	CPU-5 XCON	CPU 5.0.0,Ker 5.0.0, Rev A0								
	C2	880360	002022	CPU-5 XCON	CPU 5.0.0,Ker 5.0.0, Rev A0								
	P1												
	P2												
	P3												
	W1	801060	036245	WAN DUAL	Rev E4	81130	031328	DSX	A1	81130	031545	DSX	A1
	W2												
W3													
W4	801460	000245	WAN-R DUAL	Rev E1	811	036777	DSX	F0	811	036747	DSX	F0	
F1	8901	031547	POWER SUPPLY, AC	Rev H9									
F2	8901	043626	POWER SUPPLY, AC	Rev H9									
B A C K		Card Slot Module				Plug-In							
	Card Slot	Part No.	Serial No.	Description	Firmware/Board Ver	Part No.	Serial	Item	Version				
	IF	892360	001794	INF+M T1E1*8	Rev A1								
	U1												
	U2	811960	024021	E&M 4W*8	Rev F2								
	U3	811960	024006	E&M 4W*8	Rev F2								
	U4	811960	024013	E&M 4W*8	Rev F2								
	U5												
	U6	810860	001740	E&M 2W*8	A5								
	U7												
	U8	822560	003342	SRU-LD 232*10	Fw 1.2, KER 1.0, Rev B2								
	R1												
	R2												
	R3												
	R4												
R5													